



FINAL
Hazardous Building
Materials Assessment
(Pre-construction)

Kilbride Public School
6611 Panton Street, Burlington,
Ontario

Prepared for:

Halton District School Board
2050 Guelph Line
Burlington, Ontario, L7P 5A8

April 14, 2025

Pinchin File: 352316.001

**Hazardous Building Materials Assessment (Pre-construction)**

Kilbride Public School, 6611 Panton Street, Burlington, Ontario

Halton District School Board

April 14, 2025

Pinchin File: 352316.001

Issued to: Halton District School Board
Issued on: April 14, 2025
Pinchin File: 352316.001
Issuing Office: Hamilton, ON
Primary Pinchin Contact: Jessica Cozzitorto, Team Leader
905.577.6206
jcozzitorto@pinchin.com

Author: Ben Weir
Project Technologist

Reviewer: Damian Palus, C.E.T.
Operations Manager

EXECUTIVE SUMMARY

Halton District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct a hazardous building materials assessment at Kilbride Public School located at 6611 Panton Street, Burlington, Ontario.

Pinchin performed the assessment on February 10, 2025 with return visits on February 18 and March 10, 2025.

The objective of the assessment was to identify specified hazardous building materials in preparation for building renovation. The proposed work as identified by the Client includes the replacement of flooring in several classrooms, a new universal washroom, and the replacement of select interior and exterior doors, as shown on the draft demolition details drawing provided by the Client (dated February 10, 2025).

The results of this assessment are intended for use with properly developed work specifications.

SUMMARY OF FINDINGS

The following is a summary of significant findings; refer to the body of the report for detailed findings:

Asbestos:

- Pipe insulation
- Vermiculite
- Textured plaster
- Asbestos cement products
- Vinyl floor tiles and mastic
- Caulking and putty
- Roofing materials (presumed)
- Sink undercoating
- Refractory (presumed)

Lead:

- Lead is present in paints and coatings.
- Lead acid batteries in emergency lights and fire alarm panels

Silica: Crystalline silica is present in concrete and other materials such as masonry and mortar.

Mercury: Liquid mercury is present in thermostat ampules.

Polychlorinated Biphenyls (PCBs): Caulking present at interior door frames.

Mould and Water Damage: Visible mould and water damage was not observed.

SUMMARY OF RECOMMENDATIONS

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations.

1. Conduct further investigation of the following items, which was not completed during this assessment:
 - a. Assessment and sampling of areas and materials outside of the scope of work area for this project if the scope of work changes prior to renovation.
 - b. Sampling of any items listed as exclusions in this report, prior to disturbance.
2. Do not disturb suspected hazardous building materials discovered during the planned work, which have not been identified in this report and arrange for further evaluation and testing.
3. Remove and properly dispose of asbestos-containing materials prior to renovation activities.
4. Remove and properly dispose of PCB caulking.
5. Recycle mercury-containing thermostats if removed from service.
6. Follow appropriate safe work procedures when handling or disturbing asbestos, lead, PCBs, and silica.

This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.

TABLE OF CONTENTS

1.0	INTRODUCTION AND SCOPE	1
1.1	Scope of Assessment	1
2.0	METHODOLOGY	2
3.0	BACKGROUND INFORMATION	2
3.1	Building Description	2
3.2	Existing Reports	2
4.0	FINDINGS	2
4.1	Asbestos	3
4.2	Lead	17
4.3	Silica	22
4.4	Mercury	22
4.5	Polychlorinated Biphenyls	22
4.6	Mould and Water Damage	24
5.0	RECOMMENDATIONS	24
5.1	General	24
5.2	Building Renovation Work	25
6.0	TERMS AND LIMITATIONS	26
7.0	REFERENCES	26

APPENDICES

APPENDIX I	Drawings
APPENDIX II-A	Asbestos Analytical Certificates
APPENDIX II-B	Lead Analytical Certificates
APPENDIX II-C	PCB Analytical Certificates
APPENDIX III	Methodology
APPENDIX IV	Location Summary Report
APPENDIX V	Hazardous Materials Summary Report / Sample Log
APPENDIX VI	HMIS All Data Report

1.0 INTRODUCTION AND SCOPE

Halton District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct a hazardous building materials assessment at Kilbride Public School located at 6611 Panton Street, Burlington, Ontario.

Pinchin performed the assessment on February 10, 2025 with a return visit on February 18, 2025. The surveyors were unaccompanied during the assessment. The assessed area was unoccupied at the time of the assessment.

The objective of the assessment was to identify specified hazardous building materials in preparation for building renovation activities.

The results of this assessment are intended for use with properly developed work specifications.

1.1 Scope of Assessment

The **assessed area** is limited to the portion(s) of the building to be renovated, as described by the Client, and identified in the drawings in Appendix I.

The assessment was performed to establish the type of specified hazardous building materials, locations and approximate quantities incorporated in the structure(s) and its finishes.

For the purpose of the assessment and this report, hazardous building materials are defined as follows:

- Asbestos
- Lead
- Silica
- Mercury
- Polychlorinated Biphenyls (PCBs)
- Mould

The following Designated Substances are not typically found in building materials in a composition/state that is hazardous and were not included in this assessment:

- Arsenic
- Acrylonitrile
- Benzene
- Coke oven emissions
- Ethylene oxide
- Isocyanates

- Vinyl chloride monomer

2.0 METHODOLOGY

Pinchin conducted a room-by-room assessment to identify the hazardous building materials as defined in the scope.

Destructive testing of flooring was conducted where possible (under ceramic tiles, carpets, or multiple layers of flooring). Demolition of exterior building finishes, masonry walls (chases, shafts etc.), and structural surrounds was not conducted. Sampling of roofing materials was not conducted.

For further details on the methodology including test methods, refer to Appendix III.

3.0 BACKGROUND INFORMATION

3.1 Building Description

Description Item	Details
Use	School
Number of Floors	The building is 1 storey, with a Mezzanine level in the 1984 era.
Total Area	The total area of the building is approximately 36,000 square feet.
Year of Construction	The building was constructed in 1959 with additions constructed in 1967, 1984, and 2009.
Structure	Pre-cast concrete, masonry, metal, wood
Exterior Cladding	Brick, Transite
HVAC	Radiant heating and forced air
Roof	Not assessed
Flooring	Vinyl floor tiles, carpet, terrazzo, concrete, foam sheet flooring
Interior Walls	Concrete block, drywall, plaster
Ceilings	Acoustic ceiling tiles, plaster drywall

3.2 Existing Reports

Pinchin previously prepared the following reports, which have been reviewed as part of this assessment:

- "Asbestos Assessment", September 30, 2024. Prepared by Pinchin Ltd., File No. 332085.006.

4.0 FINDINGS

The following section summarizes the findings of the assessment and provides a general description of the hazardous building materials identified. For details on approximate quantities, condition, friability,

accessibility, and locations of hazardous building materials; refer to the Hazardous Material Summary / Sample Log and All Data Report in Appendices V and VI.

Any quantities listed in this report or data tables are estimated based on visual approximations only and are subject to variation.

Not all materials listed in the HMIS data reports are present within the assessed area or applicable to the scope of the renovation project. Refer to the findings below for materials that are present and specific to this project.

4.1 Asbestos

4.1.1 Pipe Insulation

Parging cement, containing chrysotile asbestos, is present on pipe fittings (elbows, headers, hangers etc.) in the 1959 and 1967 sections (samples S0026, S0046, S0047, and S0048, photos 1 and 2).

Sweatwrap insulation, (brown layered paper) containing chrysotile asbestos, is present on straight sections of cold system pipes in the 1959 section (samples S0023, photo 3).

Tar present below silver pipe wrapping on fibreglass insulation does not contain asbestos (sample S0065A-C, photo 4).

Remaining pipes are insulated with fibreglass, or other non-asbestos insulation such as mineral fibre or elastomeric foam insulation.

Pipes insulated with asbestos-containing insulations may be present in inaccessible spaces such as above solid ceilings, in chases, in column enclosures and within shafts.



Photo 1



Photo 2



Photo 3



Photo 4

4.1.2 Duct Insulation and Mastic

Ducts are either uninsulated or insulated with non-asbestos fibreglass (foil-faced or canvas jacketing).

Red duct mastic present at seams / joints on the ducts in the Mechanical Room (Location 120) does not contain asbestos due to the material of manufacture (silicone, photo 1).



Photo 1

4.1.3 Mechanical Equipment Insulation

Exterior of mechanical equipment (hot water tanks and boilers) is uninsulated (photos 1 and 2).

Fiberglass insulation is presumed within the hot water tank and boilers.



Photo 1



Photo 2

4.1.4 Vermiculite

Destructive testing was conducted of a representative selection of masonry block walls. The locations of destructive testing have been indicated on the drawings in Appendix I. Findings are as follows:

Description	Locations	Sample Number	Asbestos	Photo
Vermiculite in exterior concrete block walls	1967 era	S0022	Yes	
Vermiculite observed in inaccessible cavities and cracks	1959 era	S0078	Yes	

Description	Locations	Sample Number	Asbestos	Photo
No vermiculite observed in wall cavities	Library 116	N/A	N/A	
No vermiculite observed in interior wall cavities	Office / Washroom 126	N/A	N/A	

4.1.5 Acoustic Ceiling Tiles

Ceiling tiles are non-asbestos based on previous sampling (samples S0042, S0043, S0044, S0045), the date of manufacture determined from the date stamp applied to the top of the tiles (2000's), or the composition of the tiles (fibreglass).

4.1.6 Plaster and Stucco

Textured plaster, containing chrysotile asbestos is present as an exterior soffit above Door #3 outside Corridor 141 (Exterior location 150, samples S0037, photo 1). Overspray from the asbestos-containing plaster is present above the ceiling at light fixture openings, on the deck, ducts and within junction boxes.

Rough plaster present on beams throughout the 1967 era does not contain asbestos (samples S0036).



Photo 1

4.1.7 Drywall Joint Compound

Drywall joint compound present on wall and ceiling finishes throughout the assessed area does not contain asbestos (samples S0038, S0039, and S0040, photos 1 and 2).

Asbestos in drywall joint compound was banned in Canada in 1980. Drywall joint compound in the kindergarten addition (2009 addition) was installed on or after 2009 and is presumed to contain no asbestos.



Photo 1



Photo 2

4.1.8 Asbestos Cement Products

Transite board, containing chrysotile asbestos, is present above windows in Room 115 (sample S0025, photo 1).

Transite board, confirmed to contain asbestos based on visual observation, is present as exterior fascia over Door #1 Exterior (Location 151) and exterior of the 1959 era of construction (photos 2-4).



Photo 1



Photo 2



Photo 3







Photo 4

4.1.9 Vinyl Floor Tiles and Mastic

The following is a summary of vinyl floor tiles and mastic present.

Description	Sample Number	Asbestos (Tile / Mastic)	Locations	Photo
9"x9", beige with white and brown streaks	S0001 (Tile) S0002 (Mastic)	Chrysotile / None detected	Classroom 108 Classroom 109 (1959 era)	

Description	Sample Number	Asbestos (Tile / Mastic)	Locations	Photo
9"x9", green	S0031 (Tile) S0003 (Mastic)	Chrysotile / None detected	Classroom 102 Classroom 103 (1959 era)	
9"x9", red and beige (concealed below carpet)	N/A	Presumed / Presumed	Library 116 (1959 era)	
12"x12", dark beige with dark beige fleck	S0004 (Tile) S0009 (Mastic)	None detected / None detected	Classroom 105 Classroom 106 (1984 era)	
12"x12", light green	S0032 (Tile) S0008 (Mastic)	None detected / None detected	Classroom 104 (1959 era)	
Black baseboards	S0012 and S0041	No / None detected	Throughout	
Brown baseboards	S0028 / S0013	None detected / None detected	Classroom 105 Classroom 106 (1959 era)	

Description	Sample Number	Asbestos (Tile / Mastic)	Locations	Photo
12"x12", light beige with beige flecks	S0029 (Tile) S0010 & S0059 (Mastic)	None detected / None detected	Classroom 110 Classroom 111 Classroom 112 Classroom 114 Classroom 115 Storage 127 (1967 era, 1959 era)	
12"x12", dark beige with dark beige flecks	S0030 (Tile) S0062 (Mastic)	None detected / None detected	Kitchen 128 Washroom 126A (1967 era, 1984 era)	
12"x12", cream/wheat coloured with purple flecks	S0034 (Tile)	None detected	Staff Room 125 and 125A (1967 era)	
12"x12", beige with grey and brown streaks	S0060 (Tile and Mastic)	None detected / Chrysotile	Office 126 (1967 era)	
12"x12", white/beige with beige flecks	S0033 (Tile) S0056 (Mastic)	None detected / None detected	Classroom 107 Office 121 (1959 era)	
12"x12", white with black streaks (Concealed under carpet)	S0061A and B (Tile and Mastic)	None detected / None detected	Classroom 112 Classroom 114 (1967 era)	

Description	Sample Number	Asbestos (Tile / Mastic)	Locations	Photo
12"x12", white with black streaks (residual inside/under radiators and or edges/ perimeter of rooms)	S0061C (Tile and Mastic)	Chrysotile / None detected	Staff Room 125 and 125A (1967 era)	
12"x12", blue with blue flecks	N/A	None (2009)	Classroom 149 (2009 era)	
12"x12", grey with beige flecks	S0077 (Tile and Mastic)	None detected / None detected	Corridor 127 (1967 era)	

4.1.10 Levelling Compound

Levelling compound associated with vinyl floor tiles and mastic in Classroom 111 does not contain asbestos (samples S0059A-C, layer 2).

Levelling compound below foam flooring in Gymnasium 132 does not contain asbestos (samples S0069A-C).

4.1.11 Caulking and Putty


The following is a summary of caulking and putty sampled.

Material, Description and Application	Sample Location	Sample Number	Asbestos	Photo
Window putty in doors and panels, associated with double doors at Door #1	Corridor 143 (1959 era)	S0055	Yes	
Interior caulking around door frames, associated with Door #1 and #12 (1959 era)	Corridor 143 (1959 era)	S0057	No	
Exterior caulking around door frames and window panels, associated with Door #1, #12, and the library (1959 era)	Exterior 151 (1959 era)	S0058	Yes	
Interior caulking around door frames, associated with doors in the 1967 era	Office 126 Classroom 111 Corridor 141 (1959 era)	S0063	No	
Window putty in doors and panels, associated with doors in the 1967 era	Corridor 141 Office 126 (1959 era)	S0064	Yes	

Material, Description and Application	Sample Location	Sample Number	Asbestos	Photo
Window putty in doors and panels, associated with Door #2 and #11	Corridor 145 Corridor 140 (1984 era)	S0066	Yes	
Exterior caulking around door frames, associated with Door #2, #8, #9, and #11	Exterior 152 (1984 era)	S0067	Yes	
Interior caulking around door frames, associated with Door #2, #8, #9, and #11	Corridor 140 Gymnasium 132 Corridor 145 (1984 era)	S0068	Yes	
Caulking, grey, in between pre-cast concrete decking (Siporex)	Throughout assessed area	S0024	None detected	
Exterior caulking around door frames, associated with Door #3, #4, and #5	Exterior 150 (1967 era)	S0074	Yes	

4.1.12 Other Building Materials

The following is a summary of other materials sampled or present.

Description	Sample Location (Location #)	Sample Number	Asbestos	Photo
Paint on concrete block	Throughout assessed area	S0016D-G S0017G-G S0018D-G	None detected	
Gold sink undercoating	Classroom 105 Classroom 128	S0049A-C	Chrysotile	
Gaskets between flanges of boiler connections	Mechanical Room 120	S0072A-C	None detected	
Refractory brick in kiln (assumed present, inaccessible)	Classroom 106	N/A	Presumed	

Description	Sample Location (Location #)	Sample Number	Asbestos	Photo
Roofing asphalt and tar applied as a firestop material	Mechanical Room 120, around duct vent through roof	S0073	None detected	
Terrazzo floors	Corridor 141 Corridor 145	S0070	None detected	
Parging on foundation	Exterior 151 (1959 era)	S0071	None detected	
Styrofoam in spandrel panels	Library Exterior 151 (1959 era)	N/A	None	
Mortar at masonry	All eras of construction	S0019, S0020, S0021, S0052, S0053, S0054	None	

Description	Sample Location (Location #)	Sample Number	Asbestos	Photo
				
Tar/roofing on canopy roof	Exterior 151 (1959 era)	S0075	None	
Tar on roof penetration above mechanical room	Exterior 151 (1959 era)	S0076	None	
Roofing materials (1959, 1967, 1984, 2009)	Exterior 158	Not Sampled	Presumed	

4.1.13 Excluded Materials

The following is a list of materials which may contain asbestos and was excluded from the assessment.

These materials are presumed to contain asbestos until otherwise proven by sampling and analysis:

- Roofing felts and tar, mastics where not tested
- Chalkboard and tackboard mastics
- Electrical components
- Moulded plastic components (laboratory bench tops)
- Refractory materials and insulations in boilers, incinerators, and stacks
- Mechanical packing, ropes, and gaskets

- Adhesives and mastics outside assessed area
- Caulking and putties outside assessed area
- Fire resistant doors
- Sealants on pipe threads

4.2 Lead

4.2.1 Paints and Surface Coatings


The following table summarizes the analytical results of paints sampled.

Sample Number	Colour, Substrate Description	Sample Location	Lead (%)	Photo
L0001	Grey on concrete floor	Mechanical Room (Location 120)	0.40	
L0002	Light green on concrete block	Mechanical Room (Location 120)	0.29	
L0003	Blue on metal pipe	Mechanical Room (Location 120)	0.23	

Sample Number	Colour, Substrate Description	Sample Location	Lead (%)	Photo
L0004	Yellow on metal pipe	Mechanical Room (Location 120)	0.011	
L0005	Light beige on concrete block	Classroom / Storage (Location 105)	0.0043	
L0006	Light pink on concrete block	Classroom (Location 114)	0.14	
L0007	Cream on concrete block	Office / Washroom (Location 126)	0.13	

Sample Number	Colour, Substrate Description	Sample Location	Lead (%)	Photo
L0008	Light cream on concrete block	Classroom (Location 112)	0.15	
L0009	Beige on drywall ceiling	Corridor (Location 145)	0.0024	
L0010	Blue on metal door	Exterior (Location 151)	0.0018	
L0011	White on wood canopy beam	Exterior (Location 151)	0.97	

Sample Number	Colour, Substrate Description	Sample Location	Lead (%)	Photo
L0012	Brown on wood canopy deck	Exterior (Location 151)	0.26	
L0013	White on drywall soffit	Exterior (Location 150)	0.0021	
L0014	Cream/blue on concrete block	Corridor (Location 140)	0.0024	
L0015	White on metal cushion tank	Mechanical Room (Location 120)	0.052	

Sample Number	Colour, Substrate Description	Sample Location	Lead (%)	Photo
L0016	Cream on concrete block	Corridor (Location 143)	0.00043	

Results above 0.1% (1,000 mg/kg) are considered lead-containing, and over 0.5% (5,000 mg/kg) are considered lead-based.

Results less than or equal to 0.1% (1,000 mg/kg), but equal to or greater than 0.009% (90 mg/kg), are considered low-level lead paints or surface coatings in accordance with the EACC guideline.

4.2.2 Lead Products and Applications

Lead-containing batteries are present in emergency lighting and fire control panels (photo 1).



Photo 1

4.2.3 Excluded Lead Materials

Lead is known to be present in several materials which were not assessed or sampled. The following materials, where found, should be presumed to contain lead.

- Electrical components, including wiring connectors, grounding conductors, and solder
- Solder on pipe connections

4.3 Silica

Crystalline silica is assumed to be a component of the following materials where present in the building.

- Concrete
- Masonry and mortar
- Plaster
- Refractory or ceramic materials
- Asphalt

4.4 Mercury

4.4.1 Mercury-Containing Devices

Liquid mercury is present in thermostats (photo 1) and is assumed present in laboratory drainpipes in Classroom 105 (photo 1).



Photo 1

4.5 Polychlorinated Biphenyls

4.5.1 Caulking and Sealants

The following table presents a summary of caulking sampled:

Material, Colour, Application	Sample Location (Location #)	Sample Number	PCB (mg/kg)	Photo
Caulking, composite, interior door frames	1967 Era of construction	P0001	157	 
Caulking, composite of exterior door frames	1967 Era of construction	P0002	24	
Caulking, composite of spandrel panels and exterior door frames	1959 Era of construction	P0003	0.2	

Material, Colour, Application	Sample Location (Location #)	Sample Number	PCB (mg/kg)	Photo
Caulking, composite of interior door frames	1959 Era of construction	P0004	0.7	

Caulking highlighted in the table above is considered a PCB solid based on the threshold (50 mg/kg).

4.5.2 *Lighting Ballasts*

Based on the presence of Light Emitting Diode (LED) lamps, the fixtures will not contain PCB ballasts.

4.5.3 *Transformers*

All transformers in the building are dry type transformers and do not contain PCB-containing dielectric fluids; however, may contain capacitors, which could not be assessed for PCBs as the equipment was in service.

4.5.4 *Excluded PCB Materials*

PCBs are known to be present in several materials and equipment which were not assessed or sampled. The following materials, where found, should be presumed to contain PCBs until sampling proves otherwise.

- Capacitors within or associated with electrical equipment
- Oil impregnated cables

4.6 **Mould and Water Damage**

Visible mould growth and water damage was not found during the assessment.

5.0 RECOMMENDATIONS

5.1 **General**

1. If suspected hazardous building materials are discovered during the planned work, which are not identified in this report, do not disturb, and arrange for further testing and evaluation.

2. Conduct further investigation of the following items, areas, or locations, which were not completed during this assessment:
 - a. Assessment and sampling of areas and materials outside of the scope of work area for this project if the scope of work changes prior to renovation.
 - b. Any items listed as exclusions in this report, prior to disturbance.
3. Provide this report and the detailed plans and specifications to the contractor prior to bidding or commencing work.
4. Retain a qualified consultant to specify, observe and document the successful removal of hazardous materials.
5. Update the asbestos inventory upon completion of the abatement and removal of asbestos-containing materials and any other relevant findings.

5.2 Building Renovation Work

The following recommendations are made regarding renovation work involving the hazardous materials identified.

5.2.1 Asbestos

Remove asbestos-containing materials (ACM) prior to renovation, alteration, or maintenance if ACM may be disturbed by the work. If the identified ACM will not be removed prior to commencement of the work, any potential disturbance of ACM must follow asbestos precautions appropriate for the type of work being performed.

Asbestos-containing materials must be disposed of at a landfill approved to accept asbestos waste.

5.2.2 Lead

For lead-containing or lead-based paints (i.e., greater than the EACC guideline of 0.1% (1,000 mg/kg) for lead-containing paints, and 0.5% (5,000 mg/kg) for lead-based), construction disturbance may result in over-exposure to lead dust or fumes. The need for work procedures, engineering controls and personal protective equipment should be assessed on a site-specific basis to comply with Ministry of Labour, Immigration, Training and Skills Development regulations and guidelines.

For paints identified as having low levels of lead (i.e., equal to or above 0.009% (90 mg/kg) but less than or equal to the EACC guideline of 0.1% (1,000 mg/kg) for lead-containing paints) special precautions are not recommended unless aggressive disturbance (grinding, blasting, torching) is planned.

Exposure from construction disturbance of paints containing lead less than 0.009% (90 mg/kg) is assumed to be insignificant.

Lead-containing items should be recycled when taken out of service.

5.2.3 *Silica*

Construction disturbance of silica-containing products may result in excessive exposures to airborne silica, especially if performed indoors and dry. Cutting, grinding, drilling or demolition of materials containing silica should be completed only with proper respiratory protection and other worker safety precautions that comply with applicable regulations and guidelines.

5.2.4 *Mercury*

All light fixtures were observed to be LED and will not contain mercury vapor in the tubes. Recycle mercury thermostats if removed from service.

5.2.5 *PCBs*

Remove PCB caulking if affected by the renovation work. PCB caulking is a hazardous waste, package, and ship for destruction at a federally permitted facility.

5.2.6 *Mould*

No mould was observed. If mould is uncovered inside wall cavities during hand demolition, use appropriate precautions and protect workers using methods that comply with provincial guidelines

6.0 TERMS AND LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

7.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:


1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
2. Designated Substances, Ontario Regulation 490/09.


3. Lead on Construction Projects, Ministry of Labour Guidance Document.
4. The Environmental Abatement Council of Canada (EACC) Lead Guideline for Construction, Renovation, Maintenance or Repair.
5. Ministry of the Environment Regulation, R.R.O. 1990 Reg. 347 as amended.
6. Ministry of the Environment Regulation, R.R.O. 1990 Reg. 362 as amended.
7. Silica on Construction Projects, Ministry of Labour Guidance Document.
8. Alert – Mould in Workplace Buildings, Ontario Ministry of Labour.
9. PCB Regulations, SOR/2008-273, Canadian Environmental Protection Act.
10. Surface Coating Materials Regulations, SOR/2016-193, Canada Consumer Product Safety Act.
11. Consolidated Transportation of Dangerous Goods Regulations, including Amendment SOR/2019-101, Transportation of Dangerous Goods Act.
12. Mould Guidelines for the Canadian Construction Industry, Standard Construction Document CCA 82 – 2004 (Revised 2018), Canadian Construction Association.

J:\352000s\0352316.000 HALTONDISTRICT\2025Projects\HAZ\CONS\0352316.001 HDSB\KilbridePS,6611PantonSt\HAZ\ASSMT\Deliverables\HBMA\FINAL\352316.001 FINAL Report HBMA Kilbride Renovations HDSB April 14 2025.docx

Template: Master Report for Hazardous Materials Assessment (Pre-Construction), HAZ, June 19, 2024

APPENDIX I
Drawings





APPENDIX II-A
Asbestos Analytical Certificates



BUREAU
VERITAS

Your Project #: 352316.001

Site Location: ON

Your C.O.C. #: 1024116

Attention: Pinchin Asbestos Lab

Pinchin Ltd
2360 Meadowpine Blvd
Unit # 2
Mississauga, ON
CANADA L5N 6S2

Report Date: 2025/03/04

Report #: R8496382

Version: 1 - Final

CERTIFICATE OF ANALYSIS

BUREAU VERITAS JOB #: C521648

Received: 2025/02/26, 09:08

Sample Matrix: Solid
Samples Received: 51

Analyses	Quantity	Date Extracted	Date Analyzed	Laboratory Method	Analytical Method
Asbestos by PLM - 0.5 RDL (1)	51	N/A	2025/03/04	COR3SOP-00002	EPA 600R-93/116

Remarks:

Bureau Veritas is accredited to ISO/IEC 17025 for specific parameters on scopes of accreditation. Unless otherwise noted, procedures used by Bureau Veritas are based upon recognized Provincial, Federal or US method compendia such as CCME, EPA, APHA or the Quebec Ministry of Environment.

All work recorded herein has been done in accordance with procedures and practices ordinarily exercised by professionals in Bureau Veritas' profession using accepted testing methodologies, quality assurance and quality control procedures (except where otherwise agreed by the client and Bureau Veritas in writing). All data is in statistical control and has met quality control and method performance criteria unless otherwise noted. All method blanks are reported; unless indicated otherwise, associated sample data are not blank corrected. Where applicable, unless otherwise noted, Measurement Uncertainty has not been accounted for when stating conformity to the referenced standard.

Bureau Veritas liability is limited to the actual cost of the requested analyses, unless otherwise agreed in writing. There is no other warranty expressed or implied. Bureau Veritas has been retained to provide analysis of samples provided by the Client using the testing methodology referenced in this report. Interpretation and use of test results are the sole responsibility of the Client and are not within the scope of services provided by Bureau Veritas, unless otherwise agreed in writing. Bureau Veritas is not responsible for the accuracy or any data impacts, that result from the information provided by the customer or their agent.

Solid sample results, except biota, are based on dry weight unless otherwise indicated. Organic analyses are not recovery corrected except for isotope dilution methods.

Results relate to samples tested. When sampling is not conducted by Bureau Veritas, results relate to the supplied samples tested.

This Certificate shall not be reproduced except in full, without the written approval of the laboratory.

Bureau Veritas' Asbestos Laboratory is accredited by NVLAP for bulk asbestos analysis by polarized light microscopy, NVLAP Code 600136-0.

This report may not be reproduced, except in full, without the written approval of Bureau Veritas. This report may not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any other agency of the U.S. Government.

Bureau Veritas' scope of accreditation includes EPA -- 40 CFR Appendix E to Subpart E of Part 763, "Interim Method for the Determination of Asbestos in Bulk Insulation Samples" and EPA-600/R-93/116: "Method for the Determination of Asbestos in Bulk Building Materials".

Reference Method suffix "m" indicates test methods incorporate validated modifications from specific reference methods to improve performance.

* RPDs calculated using raw data. The rounding of final results may result in the apparent difference.

(1) P.O.B. - Percent of Bulk



BUREAU
VERITAS

Your Project #: 352316.001

Site Location: ON

Your C.O.C. #: 1024116

Attention: Pinchin Asbestos Lab

Pinchin Ltd
2360 Meadowpine Blvd
Unit # 2
Mississauga, ON
CANADA L5N 6S2

Report Date: 2025/03/04

Report #: R8496382

Version: 1 - Final

CERTIFICATE OF ANALYSIS

BUREAU VERITAS JOB #: C521648

Received: 2025/02/26, 09:08

When Asbestos data is reported with other data, this report contains data that are not covered by the NVLAP accreditation.

Encryption Key

Please direct all questions regarding this Certificate of Analysis to:

Nilushi Mahathantila, Project Manager
Email: Nilushi.Mahathantila@bureauveritas.com
Phone# (905) 817-5700

=====
This report has been generated and distributed using a secure automated process.

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

Total Cover Pages : 2
Page 2 of 32

Bureau Veritas 6740 Campobello Road, Mississauga, Ontario, L5N 2L8 Tel: (905) 817-5700 Toll-Free: 800-563-6266 Fax: (905) 817-5777 www.bvna.com

Microbiology testing is conducted at 6660 Campobello Rd. Chemistry testing is conducted at 6740 Campobello Rd.



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0055A,Door,Putty,Window, Door

1,Loc:143,Corridor

Bureau Veritas AOMB70
ID:

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black putty	Chrysotile 4%		Non-Fibrous

S0055B,Door,Putty,Window, Door

1,Loc:143,Corridor

Bureau Veritas AOMB71
ID:

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1			N/A		

Comment: Not Analyzed - Positive Stop

S0055C,Door,Putty,Window, Door

1,Loc:143,Corridor

Bureau Veritas AOMB72
ID:

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1			N/A		

Comment: Not Analyzed - Positive Stop

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0056A,Floor,Mastic, Black,Loc:107,Classroom

[ONLY ANALYZE MASTIC]

Bureau Veritas AOMB73
ID:

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

S0056B,Floor,Mastic, Black,Loc:107,Classroom

[ONLY ANALYZE MASTIC]

Bureau Veritas AOMB74
ID:

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

S0056C,Floor,Mastic, Black,Loc:107,Classroom

[ONLY ANALYZE MASTIC]

Bureau Veritas AOMB75
ID:

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0057A,Door,Caulking,Door 1,Loc:143,Corridor

Bureau Veritas	AOMB76	ID:	Date Analyzed:	2025/03/04
Layer 1	100	P.O.B	Sample Morphology	Asbestos Other Fibres Particulate

Homogeneous grey caulking Not Detected Non-Fibrous

S0057B,Door,Caulking,Door 1,Loc:143,Corridor

Bureau Veritas	AOMB77	ID:	Date Analyzed:	2025/03/04
Layer 1	100	P.O.B	Sample Morphology	Asbestos Other Fibres Particulate

Homogeneous grey caulking Not Detected Non-Fibrous

S0057C,Door,Caulking,Door 1,Loc:143,Corridor

Bureau Veritas	AOMB78	ID:	Date Analyzed:	2025/03/04
Layer 1	100	P.O.B	Sample Morphology	Asbestos Other Fibres Particulate

Homogeneous grey caulking Not Detected Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0058A,Caulking,Library Window

Panels,Loc:150,Exterior

Bureau Veritas ID: AOMB79

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey/brown caulking	Chrysotile 1%		Non-Fibrous

S0058B,Door,Caulking,Door 12,Loc:150,Exterior

Bureau Veritas ID: AOMB80

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1			N/A		

Comment: Not Analyzed - Positive Stop

S0058C,Door,Caulking,Door 1,Loc:150,Exterior

Bureau Veritas ID: AOMB81

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1			N/A		

Comment: Not Analyzed - Positive Stop

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0059A,Floor,Mastic, And Levelling,Loc:111,Classroom [ONLY ANALYZE MASTIC/LEVELLING]

Bureau Veritas AOMB82
ID:

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	10	Homogeneous black mastic	Not Detected		Non-Fibrous
Layer 2	90	Homogeneous grey levelling compound	Not Detected		Non-Fibrous

S0059B,Floor,Mastic, And Levelling,Loc:111,Classroom [ONLY ANALYZE MASTIC/LEVELLING]

Bureau Veritas AOMB83
ID:

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	10	Homogeneous black mastic	Not Detected		Non-Fibrous
Layer 2	90	Homogeneous grey levelling compound	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0059C,Floor,Mastic, And Levelling,Loc:111,Classroom [ONLY ANALYZE MASTIC/LEVELLING]

Bureau Veritas AOMB84
ID:

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	10	Homogeneous black mastic	Not Detected		Non-Fibrous
Layer 2	90	Homogeneous grey levelling compound	Not Detected		Non-Fibrous

S0060A,Floor,VFT And Mastic,12x12 Beige W Grey And Brown Streaks,Loc:126,Office

Bureau Veritas AOMB85
ID:

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	95	Homogeneous grey vinyl floor tile	Not Detected		Non-Fibrous
Layer 2	5	Homogeneous black mastic	Chrysotile	0.5%	Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0060B,Floor,VFT And Mastic,12x12 Beige W Grey And Brown Streaks,Loc:126,Office

Bureau Veritas ID: AOMB86

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	95	Homogeneous grey vinyl floor tile	Not Detected		Non-Fibrous
Layer 2	5	Homogeneous black mastic	N/A		
Comment: Not Analyzed - Positive Stop					

S0060C,Floor,VFT And Mastic,12x12 Beige W Grey And Brown Streaks,Loc:126,Office

Bureau Veritas ID: AOMB87

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	95	Homogeneous grey vinyl floor tile	Not Detected		Non-Fibrous
Layer 2	5	Homogeneous black mastic	N/A		
Comment: Not Analyzed - Positive Stop					

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0061A,VFT And Mastic,12x12

White,Loc:112,Classroom [DO NOT ANALYZE

YELLOW MASTIC]

Bureau Veritas AOMB88
ID:

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	95	Homogeneous light grey vinyl floor tile	Not Detected		Non-Fibrous
Layer 2	5	Homogeneous black mastic	Not Detected		Non-Fibrous

S0061B,VFT And Mastic,12x12

White,Loc:114,Classroom [DO NOT ANALYZE

YELLOW MASTIC]

Bureau Veritas AOMB89
ID:

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	95	Homogeneous light grey vinyl floor tile	Not Detected		Non-Fibrous
Layer 2	5	Homogeneous black mastic	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0061C,VFT And Mastic,12x12 White,In

Radiator,Loc:125,Staff Room

Bureau Veritas ID: AOMB90

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	95	Homogeneous grey vinyl floor tile	Chrysotile 1%		Non-Fibrous
Layer 2	5	Homogeneous black mastic	Not Detected		Non-Fibrous

S0062A,Floor,Mastic,Loc:128,Kitchen [ONLY

ANALYZE MASTIC]

Bureau Veritas ID: AOMB91

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

S0062B,Floor,Mastic,Loc:128,Kitchen [ONLY

ANALYZE MASTIC]

Bureau Veritas ID: AOMB92

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0062C,Floor,Mastic,Loc:128,Kitchen [ONLY ANALYZE MASTIC]

Bureau Veritas AOMB93
ID:

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

S0063A,Wall,Door,Caulking,Loc:126,Office / Washroom

Bureau Veritas AOMB94
ID:

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous beige caulking	Not Detected	Talc 20%	Non-Fibrous

S0063B,Wall,Door,Caulking,Loc:111,Classroom

Bureau Veritas AOMB95
ID:

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous beige caulking	Not Detected	Talc 20%	Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0063C, Wall,Door,Caulking,Loc:141,Corridor

Bureau Veritas	AOMB96	ID:	Date Analyzed:	2025/03/04			
Layer 1	100	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate	
			Homogeneous beige caulk	Not Detected	Talc	20%	Non-Fibrous

S0064A, Window,Putty,Loc:141,Corridor

Bureau Veritas	AOMB97	ID:	Date Analyzed:	2025/03/04		
Layer 1	100	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
			Homogeneous black putty	Not Detected		Non-Fibrous

S0064B, Window,Putty,Loc:126,Office

Bureau Veritas	AOMB98	ID:	Date Analyzed:	2025/03/04		
Layer 1	100	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
			Homogeneous grey putty	Chrysotile	2%	Non-Fibrous

S0064C, Window,Putty,Loc:141,Corridor

Bureau Veritas	AOMB99	ID:	Date Analyzed:	2025/03/04		
Layer 1	100	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
			Homogeneous grey cementitious material	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0065A,Piping,Tar,Loc:126,Office / Washroom

Bureau Veritas	AOMC00	ID:	Date Analyzed:	2025/03/04			
Layer 1	100	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate	
			Homogeneous black tar	Not Detected	Mineral Wool	15%	Non-Fibrous

S0065B,Piping,Tar,Loc:126,Office / Washroom

Bureau Veritas	AOMC01	ID:	Date Analyzed:	2025/03/04			
Layer 1	100	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate	
			Homogeneous black tar	Not Detected	Mineral Wool	15%	Non-Fibrous

S0065C,Piping,Tar,Loc:126,Office / Washroom

Bureau Veritas	AOMC02	ID:	Date Analyzed:	2025/03/04			
Layer 1	100	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate	
			Homogeneous black tar	Not Detected	Mineral Wool	15%	Non-Fibrous

S0066A,Window,Putty,Loc:145,Corridor

Bureau Veritas	AOMC03	ID:	Date Analyzed:	2025/03/04		
Layer 1	100	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
			Homogeneous black putty	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0066B, Window, Putty, Loc:145, Corridor

Bureau Veritas ID:	AOMC04				Date Analyzed: 2025/03/04
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	20	Homogeneous black putty	Not Detected		Non-Fibrous
Layer 2	80	Homogeneous grey putty	Chrysotile	3%	Non-Fibrous

S0066C, Window, Putty, Loc:140, Corridor

Bureau Veritas ID:	AOMC05				Date Analyzed: 2025/03/04
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1			N/A		
Comment: Not Analyzed - Positive Stop					

S0067A, Door, Caulking, Door 2, Loc:150, Exterior

Bureau Veritas ID:	AOMC06				Date Analyzed: 2025/03/04
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	50	Homogeneous grey caulking	Not Detected		Non-Fibrous
Layer 2	50	Homogeneous brown caulking	Chrysotile	1%	Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0067B,Door,Caulking,Door 2,Loc:150,Exterior

Bureau Veritas ID:	AOMC07				Date Analyzed: 2025/03/04
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	50	Homogeneous grey caulking	Not Detected		Non-Fibrous
Layer 2	50	Homogeneous brown caulking	N/A		
Comment: Not Analyzed - Positive Stop					

S0067C,Door,Caulking,Door 11,Loc:150,Exterior

Bureau Veritas ID:	AOMC08				Date Analyzed: 2025/03/04
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	30	Homogeneous beige caulking	Chrysotile	1%	Non-Fibrous
Layer 2	70	Homogeneous brown caulking	N/A		
Comment: Not Analyzed - Positive Stop					

S0068A,Door,Caulking,Door 11,Loc:140,Corridor

Bureau Veritas ID:	AOMC09				Date Analyzed: 2025/03/04
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey caulking	Chrysotile	1%	Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0068B,Door,Caulking,Door 9,Loc:132,Gymnasium

Bureau Veritas	AOMC10	Date Analyzed:	2025/03/04															
ID:																		
<table><thead><tr><th>P.O.B</th><th>Sample Morphology</th><th>Asbestos</th><th>Other Fibres</th><th>Particulate</th></tr></thead><tbody><tr><td>Layer 1</td><td></td><td>N/A</td><td></td><td></td></tr><tr><td colspan="5">Comment: Not Analyzed - Positive Stop</td></tr></tbody></table>				P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate	Layer 1		N/A			Comment: Not Analyzed - Positive Stop				
P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate														
Layer 1		N/A																
Comment: Not Analyzed - Positive Stop																		

S0068C,Door,Caulking,Door 2,Loc:145,Corridor

Bureau Veritas	AOMC11	Date Analyzed:	2025/03/04															
ID:																		
<table><thead><tr><th>P.O.B</th><th>Sample Morphology</th><th>Asbestos</th><th>Other Fibres</th><th>Particulate</th></tr></thead><tbody><tr><td>Layer 1</td><td></td><td>N/A</td><td></td><td></td></tr><tr><td colspan="5">Comment: Not Analyzed - Positive Stop</td></tr></tbody></table>				P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate	Layer 1		N/A			Comment: Not Analyzed - Positive Stop				
P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate														
Layer 1		N/A																
Comment: Not Analyzed - Positive Stop																		

S0069A,Floor,Floor Levelling Compound,Loc:132,Gymnasium

Bureau Veritas	AOMC12	Date Analyzed:	2025/03/04															
ID:																		
<table><thead><tr><th>P.O.B</th><th>Sample Morphology</th><th>Asbestos</th><th>Other Fibres</th><th>Particulate</th></tr></thead><tbody><tr><td>Layer 1</td><td>100</td><td>Homogeneous brown levelling compound</td><td>Not Detected</td><td>Non-Fibrous</td></tr><tr><td colspan="5"></td></tr></tbody></table>				P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate	Layer 1	100	Homogeneous brown levelling compound	Not Detected	Non-Fibrous					
P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate														
Layer 1	100	Homogeneous brown levelling compound	Not Detected	Non-Fibrous														

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0069B,Floor,Floor Levelling Compound,Loc:132,Gymnasium

Bureau Veritas AOMC13
ID:

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous brown levelling compound	Not Detected		Non-Fibrous

S0069C,Floor,Floor Levelling Compound,Loc:132,Gymnasium

Bureau Veritas AOMC14
ID:

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous brown levelling compound	Not Detected		Non-Fibrous

S0070A,Floor,Terrazzo,Loc:141,Corridor

Bureau Veritas AOMC15
ID:

Date Analyzed: 2025/03/04

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	90	Homogeneous beige terrazzo flooring	Not Detected		Non-Fibrous
Layer 2	10	Homogeneous grey cementitious material	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0070B,Floor,Terrazzo,Loc:141,Corridor

Bureau Veritas ID:	AOMC16	Date Analyzed: 2025/03/04			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	90	Homogeneous beige terrazzo flooring	Not Detected		Non-Fibrous
Layer 2	10	Homogeneous grey cementitious material	Not Detected		Non-Fibrous

S0070C,Floor,Terrazzo,Loc:145,Corridor

Bureau Veritas ID:	AOMC17	Date Analyzed: 2025/03/04			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	90	Homogeneous beige terrazzo flooring	Not Detected		Non-Fibrous
Layer 2	10	Homogeneous grey cementitious material	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0071A, Wall, Plaster, Parging On Foundation, Outside Library, Loc:150, Exterior

Bureau Veritas	AOMC18	Date Analyzed:	2025/03/04
P.O.B	Sample Morphology	Asbestos	Other Fibres
Layer 1 10	Homogeneous white cementitious material	Not Detected	Particulate Non-Fibrous
Layer 2 90	Homogeneous grey cementitious material	Not Detected	Non-Fibrous

S0071B, Wall, Plaster, Parging On Foundation, Outside Library, Loc:150, Exterior

Bureau Veritas	AOMC19	Date Analyzed:	2025/03/04
P.O.B	Sample Morphology	Asbestos	Other Fibres
Layer 1 10	Homogeneous white cementitious material	Not Detected	Particulate Non-Fibrous
Layer 2 90	Homogeneous grey cementitious material	Not Detected	Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

**S0071C,Wall,Plaster,Parging On Foundation,
Outside Library,Loc:150,Exterior**

Bureau Veritas ID: AOMC20

Date Analyzed: 2025/03/04

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	10	Homogeneous white cementitious material	Not Detected		Non-Fibrous
Layer 2	90	Homogeneous grey cementitious material	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

TEST SUMMARY

Bureau Veritas ID: AOMB70 **Collected:** 2025/02/14
Sample ID: S0055A,Door,Putty,Window, Door 1,Loc:143,Corridor **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB71 **Collected:** 2025/02/14
Sample ID: S0055B,Door,Putty,Window, Door 1,Loc:143,Corridor **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB72 **Collected:** 2025/02/14
Sample ID: S0055C,Door,Putty,Window, Door 1,Loc:143,Corridor **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB73 **Collected:** 2025/02/14
Sample ID: S0056A,Floor,Mastic, Black,Loc:107,Classroom [ONLY ANALYZE MASTIC] **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB74 **Collected:** 2025/02/14
Sample ID: S0056B,Floor,Mastic, Black,Loc:107,Classroom [ONLY ANALYZE MASTIC] **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB75 **Collected:** 2025/02/14
Sample ID: S0056C,Floor,Mastic, Black,Loc:107,Classroom [ONLY ANALYZE MASTIC] **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB76 **Collected:** 2025/02/14
Sample ID: S0057A,Door,Caulking,Door 1,Loc:143,Corridor **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

TEST SUMMARY

Bureau Veritas ID: AOMB77 **Collected:** 2025/02/14
Sample ID: S0057B,Door,Caulking,Door 1,Loc:143,Corridor **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB77 Dup **Collected:** 2025/02/14
Sample ID: S0057B,Door,Caulking,Door 1,Loc:143,Corridor **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB78 **Collected:** 2025/02/14
Sample ID: S0057C,Door,Caulking,Door 1,Loc:143,Corridor **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB79 **Collected:** 2025/02/14
Sample ID: S0058A,Caulking,Library Window Panels,Loc:150,Exterior **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB80 **Collected:** 2025/02/14
Sample ID: S0058B,Door,Caulking,Door 12,Loc:150,Exterior **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB81 **Collected:** 2025/02/14
Sample ID: S0058C,Door,Caulking,Door 1,Loc:150,Exterior **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB82 **Collected:** 2025/02/14
Sample ID: S0059A,Floor,Mastic, And Levelling,Loc:111,Classroom [ONLY ANALYZE MASTIC/LEVELLING] **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

TEST SUMMARY

Bureau Veritas ID: AOMB83 **Collected:** 2025/02/14
Sample ID: S0059B,Floor,Mastic, And Levelling,Loc:111,Classroom [ONLY ANALYZE MASTIC/LEVELLING] **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB84 **Collected:** 2025/02/14
Sample ID: S0059C,Floor,Mastic, And Levelling,Loc:111,Classroom [ONLY ANALYZE MASTIC/LEVELLING] **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB85 **Collected:** 2025/02/14
Sample ID: S0060A,Floor,VFT And Mastic,12x12 Beige W Grey And Brown Streaks,Loc:126,Office **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB86 **Collected:** 2025/02/14
Sample ID: S0060B,Floor,VFT And Mastic,12x12 Beige W Grey And Brown Streaks,Loc:126,Office **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB87 **Collected:** 2025/02/14
Sample ID: S0060C,Floor,VFT And Mastic,12x12 Beige W Grey And Brown Streaks,Loc:126,Office **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB88 **Collected:** 2025/02/14
Sample ID: S0061A,VFT And Mastic,12x12 White,Loc:112,Classroom [DO NOT ANALYZE YELLOW MASTIC] **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB88 Dup **Collected:** 2025/02/14
Sample ID: S0061A,VFT And Mastic,12x12 White,Loc:112,Classroom [DO NOT ANALYZE YELLOW MASTIC] **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

TEST SUMMARY

Bureau Veritas ID: AOMB89 **Collected:** 2025/02/14
Sample ID: S0061B,VFT And Mastic,12x12 White,Loc:114,Classroom [DO NOT ANALYZE YELLOW MASTIC] **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB90 **Collected:** 2025/02/14
Sample ID: S0061C,VFT And Mastic,12x12 White,In Radiator,Loc:125,Staff Room **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB91 **Collected:** 2025/02/14
Sample ID: S0062A,Floor,Mastic,Loc:128,Kitchen [ONLY ANALYZE MASTIC] **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB92 **Collected:** 2025/02/14
Sample ID: S0062B,Floor,Mastic,Loc:128,Kitchen [ONLY ANALYZE MASTIC] **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB93 **Collected:** 2025/02/14
Sample ID: S0062C,Floor,Mastic,Loc:128,Kitchen [ONLY ANALYZE MASTIC] **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB94 **Collected:** 2025/02/14
Sample ID: S0063A,Wall,Door,Caulking,Loc:126,Office / Washroom **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB95 **Collected:** 2025/02/14
Sample ID: S0063B,Wall,Door,Caulking,Loc:111,Classroom **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

TEST SUMMARY

Bureau Veritas ID: AOMB96

Sample ID: S0063C,Wall,Door,Caulking,Loc:141,Corridor

Matrix: Solid

Collected: 2025/02/14

Shipped:

Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB97

Sample ID: S0064A,Window,Putty,Loc:141,Corridor

Matrix: Solid

Collected: 2025/02/14

Shipped:

Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB98

Sample ID: S0064B,Window,Putty,Loc:126,Office

Matrix: Solid

Collected: 2025/02/14

Shipped:

Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB98 Dup

Sample ID: S0064B,Window,Putty,Loc:126,Office

Matrix: Solid

Collected: 2025/02/14

Shipped:

Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMB99

Sample ID: S0064C,Window,Putty,Loc:141,Corridor

Matrix: Solid

Collected: 2025/02/14

Shipped:

Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMC00

Sample ID: S0065A,Piping,Tar,Loc:126,Office / Washroom

Matrix: Solid

Collected: 2025/02/14

Shipped:

Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMC01

Sample ID: S0065B,Piping,Tar,Loc:126,Office / Washroom

Matrix: Solid

Collected: 2025/02/14

Shipped:

Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

TEST SUMMARY

Bureau Veritas ID: AOMC02 **Collected:** 2025/02/14
Sample ID: S0065C,Piping,Tar,Loc:126,Office / Washroom **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMC03 **Collected:** 2025/02/14
Sample ID: S0066A,Window,Putty,Loc:145,Corridor **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMC04 **Collected:** 2025/02/14
Sample ID: S0066B,Window,Putty,Loc:145,Corridor **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMC05 **Collected:** 2025/02/14
Sample ID: S0066C,Window,Putty,Loc:140,Corridor **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMC06 **Collected:** 2025/02/14
Sample ID: S0067A,Door,Caulking,Door 2,Loc:150,Exterior **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMC06 Dup **Collected:** 2025/02/14
Sample ID: S0067A,Door,Caulking,Door 2,Loc:150,Exterior **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMC07 **Collected:** 2025/02/14
Sample ID: S0067B,Door,Caulking,Door 2,Loc:150,Exterior **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

TEST SUMMARY

Bureau Veritas ID: AOMC08 **Collected:** 2025/02/14
Sample ID: S0067C,Door,Caulking,Door 11,Loc:150,Exterior **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884483	N/A	2025/03/04	Jon Delos Santos

Bureau Veritas ID: AOMC09 **Collected:** 2025/02/14
Sample ID: S0068A,Door,Caulking,Door 11,Loc:140,Corridor **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad

Bureau Veritas ID: AOMC10 **Collected:** 2025/02/14
Sample ID: S0068B,Door,Caulking,Door 9,Loc:132,Gymnasium **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad

Bureau Veritas ID: AOMC11 **Collected:** 2025/02/14
Sample ID: S0068C,Door,Caulking,Door 2,Loc:145,Corridor **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad

Bureau Veritas ID: AOMC12 **Collected:** 2025/02/14
Sample ID: S0069A,Floor,Floor Levelling Compound,Loc:132,Gymnasium **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad

Bureau Veritas ID: AOMC13 **Collected:** 2025/02/14
Sample ID: S0069B,Floor,Floor Levelling Compound,Loc:132,Gymnasium **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad

Bureau Veritas ID: AOMC14 **Collected:** 2025/02/14
Sample ID: S0069C,Floor,Floor Levelling Compound,Loc:132,Gymnasium **Shipped:**
Matrix: Solid **Received:** 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

TEST SUMMARY

Bureau Veritas ID: AOMC15
Sample ID: S0070A,Floor,Terrazzo,Loc:141,Corridor
Matrix: Solid

Collected: 2025/02/14
Shipped:
Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad

Bureau Veritas ID: AOMC16
Sample ID: S0070B,Floor,Terrazzo,Loc:141,Corridor
Matrix: Solid

Collected: 2025/02/14
Shipped:
Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad

Bureau Veritas ID: AOMC17
Sample ID: S0070C,Floor,Terrazzo,Loc:145,Corridor
Matrix: Solid

Collected: 2025/02/14
Shipped:
Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad

Bureau Veritas ID: AOMC18
Sample ID: S0071A,Wall,Plaster,Parging On Foundation, Outside Library,Loc:150,Exterior
Matrix: Solid

Collected: 2025/02/14
Shipped:
Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad

Bureau Veritas ID: AOMC18 Dup
Sample ID: S0071A,Wall,Plaster,Parging On Foundation, Outside Library,Loc:150,Exterior
Matrix: Solid

Collected: 2025/02/14
Shipped:
Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad

Bureau Veritas ID: AOMC19
Sample ID: S0071B,Wall,Plaster,Parging On Foundation, Outside Library,Loc:150,Exterior
Matrix: Solid

Collected: 2025/02/14
Shipped:
Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad

Bureau Veritas ID: AOMC20
Sample ID: S0071C,Wall,Plaster,Parging On Foundation, Outside Library,Loc:150,Exterior
Matrix: Solid

Collected: 2025/02/14
Shipped:
Received: 2025/02/26

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9884484	N/A		Haseeb Ahmad



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

GENERAL COMMENTS

Results relate only to the items tested.



BUREAU
VERITAS

Bureau Veritas Job #: C521648

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: EB

VALIDATION SIGNATURE PAGE

The analytical data and all QC contained in this report were reviewed and validated by:

Dina Yousif, Analyst 2

Jon Delos Santos, Laboratory Supervisor

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

C521648

2025/02/26 09:08



NONT-2025-02-4447

eCOC Offline Template:Asbestos

This is not intended to be a paper COC. To complete your submission, please upload this file in the jobs section of the Customer Portal. Please use the Customer Portal for Composite Samples and / or Shelf-life submissions.

BURE
VERITAS

Test Selection

X Selected

TESTS

	Asbestos by P.M. - 0.1 RDL 8 hr	Asbestos by P.M. - 0.1 RDL 24 hr	Asbestos by P.M. - 0.1 RDL 96 hr	Asbestos by P.M. - 0.5 RDL 8 hr	Asbestos by P.M. - 0.5 RDL 24 hr	Asbestos by P.M. - 0.5 RDL 96 hr	Asbestos by P.M. - 1.0 RDL 8 hr	Asbestos by P.M. - 1.0 RDL 24 hr	Asbestos by P.M. - 1.0 RDL 96 hr
1. S0055A,Door,Putty,Window, Door 1,Loc:1-13,Corridor	Solid	1	2025/2/14	PM					X
2. S0055B,Door,Putty,Window, Door 1,Loc:1-13,Corridor	Solid	1	2025/2/14	PM					X
3. S0055C,Door,Putty,Window, Door 1,Loc:1-13,Corridor	Solid	1	2025/2/14	PM					X
4. S0056A,Door,Mastic,Black,Loc:10,Classroom ONLY ANALYZE MASTIC	Solid	1	2025/2/14	PM					X
5. S0056B,Door,Mastic,Black,Loc:10,Classroom ONLY ANALYZE MASTIC	Solid	1	2025/2/14	PM					X
6. S0056C,Door,Mastic,Black,Loc:10,Classroom ONLY ANALYZE MASTIC	Solid	1	2025/2/14	PM					X
7. S0057A,Door,Caulking,Door 1,Loc:1-13,Corridor	Solid	1	2025/2/14	PM					X
8. S0057B,Door,Caulking,Door 1,Loc:1-13,Corridor	Solid	1	2025/2/14	PM					X
9. S0057C,Door,Caulking,Door 1,Loc:1-13,Corridor	Solid	1	2025/2/14	PM					X
10. S0058A,Caulking,Irrn,Window,Panel,Loc:130,Exterior	Solid	1	2025/2/14	PM					X
11. S0058B,Caulking,Irrn,Window,Panel,Loc:130,Exterior	Solid	1	2025/2/14	PM					X
12. S0058C,Caulking,Irrn,Window,Panel,Loc:130,Exterior	Solid	1	2025/2/14	PM					X
13. S0059A,Door,Mastic,And,Leveling,Loc:111,Classroom (ONLY ANALYZE MASTIC/LEVELLING)	Solid	1	2025/2/14	PM					X
14. S0059B,Door,Mastic,And,Leveling,Loc:111,Classroom (ONLY ANALYZE MASTIC/LEVELLING)	Solid	1	2025/2/14	PM					X
15. S0059C,Door,Mastic,And,Leveling,Loc:111,Classroom (ONLY ANALYZE MASTIC/LEVELLING)	Solid	1	2025/2/14	PM					X
16. S0060A,Door,Mastic,And,Leveling,Loc:124,Beige,W,Gray,And,Brown,Streaks,Loc:126,Office	Solid	1	2025/2/14	PM					X
17. S0060B,Door,Mastic,And,Leveling,Loc:124,Beige,W,Gray,And,Brown,Streaks,Loc:126,Office	Solid	1	2025/2/14	PM					X
18. S0060C,Door,Mastic,And,Leveling,Loc:124,Beige,W,Gray,And,Brown,Streaks,Loc:126,Office	Solid	1	2025/2/14	PM					X
19. S0061A,VFT,And,Mastic,Loc:124,12,White,Loc:124,12,Classroom (DO NOT ANALYZE YELLOW MASTIC)	Solid	1	2025/2/14	PM					X
20. S0061B,VFT,And,Mastic,Loc:124,12,White,Loc:124,12,Classroom (DO NOT ANALYZE YELLOW MASTIC)	Solid	1	2025/2/14	PM					X
21. S0061C,VFT,And,Mastic,Loc:124,12,White,In,Radiation,Loc:125,Staff,Room	Solid	1	2025/2/14	PM					X
22. S0062A,Door,Mastic,Loc:128,Kitchen (ONLY ANALYZE MASTIC)	Solid	1	2025/2/14	PM					X
23. S0062B,Door,Mastic,Loc:128,Kitchen (ONLY ANALYZE MASTIC)	Solid	1	2025/2/14	PM					X
24. S0062C,Door,Mastic,Loc:128,Kitchen (ONLY ANALYZE MASTIC)	Solid	1	2025/2/14	PM					X
25. S0063A,Wall,Door,Caulking,Loc:126,Office, /Washroom	Solid	1	2025/2/14	PM					X
26. S0063B,Wall,Door,Caulking,Loc:126,Office, /Washroom	Solid	1	2025/2/14	PM					X
27. S0063C,Wall,Door,Caulking,Loc:126,Corridor	Solid	1	2025/2/14	PM					X
28. S0064A,Window,Panel,Loc:145,Corridor	Solid	1	2025/2/14	PM					X
29. S0064B,Window,Panel,Loc:145,Office	Solid	1	2025/2/14	PM					X
30. S0064C,Window,Panel,Loc:145,Office	Solid	1	2025/2/14	PM					X
31. S0065A,Door,Caulking,Loc:126,Office, /Washroom	Solid	1	2025/2/14	PM					X
32. S0065B,Door,Caulking,Loc:126,Office, /Washroom	Solid	1	2025/2/14	PM					X
33. S0065C,Door,Caulking,Loc:126,Office, /Washroom	Solid	1	2025/2/14	PM					X
34. S0066A,Window,Panel,Loc:145,Corridor	Solid	1	2025/2/14	PM					X
35. S0066B,Window,Panel,Loc:145,Corridor	Solid	1	2025/2/14	PM					X
36. S0066C,Window,Panel,Loc:145,Corridor	Solid	1	2025/2/14	PM					X
37. S0067A,Door,Caulking,Door 1,Loc:150,Exterior	Solid	1	2025/2/14	PM					X
38. S0067B,Door,Caulking,Door 1,Loc:150,Exterior	Solid	1	2025/2/14	PM					X
39. S0067C,Door,Caulking,Door 1,Loc:150,Exterior	Solid	1	2025/2/14	PM					X
40. S0068A,Door,Caulking,Door 1,Loc:141,Corridor	Solid	1	2025/2/14	PM					X
41. S0068B,Door,Caulking,Door 1,Loc:141,Corridor	Solid	1	2025/2/14	PM					X
42. S0068C,Door,Caulking,Door 1,Loc:141,Corridor	Solid	1	2025/2/14	PM					X
43. S0069A,Door,Irrn,Leveling,Compound,Loc:132,Gymnasium	Solid	1	2025/2/14	PM					X
44. S0069B,Door,Irrn,Leveling,Compound,Loc:132,Gymnasium	Solid	1	2025/2/14	PM					X
45. S0069C,Door,Irrn,Leveling,Compound,Loc:132,Gymnasium	Solid	1	2025/2/14	PM					X
46. S0070A,Door,Terrazo,Loc:141,Corridor	Solid	1	2025/2/14	PM					X
47. S0070B,Door,Terrazo,Loc:141,Corridor	Solid	1	2025/2/14	PM					X
48. S0070C,Door,Terrazo,Loc:141,Corridor	Solid	1	2025/2/14	PM					X
49. S0071A,Wall,Plaster,Painting,On,Foundation,Outside,Library,Loc:150,Exterior	Solid	1	2025/2/14	PM					X
50. S0071C,Wall,Plaster,Painting,On,Foundation,Outside,Library,Loc:150,Exterior	Solid	1	2025/2/14	PM					X
51. S0072C,Wall,Plaster,Painting,On,Foundation,Outside,Library,Loc:150,Exterior	Solid	1	2025/2/14	PM					X



BUREAU
VERITAS

Your Project #: 352316.001

Site Location: ON

Your C.O.C. #: 1024891

Attention: Pinchin Asbestos Lab

Pinchin Ltd
2360 Meadowpine Blvd
Unit # 2
Mississauga, ON
CANADA L5N 6S2

Report Date: 2025/03/21

Report #: R8507153

Version: 1 - Final

CERTIFICATE OF ANALYSIS

BUREAU VERITAS JOB #: C528244

Received: 2025/03/17, 10:15

Sample Matrix: Solid
Samples Received: 20

Analyses	Quantity	Date Extracted	Date Analyzed	Laboratory Method	Analytical Method
Asbestos by PLM - 0.5 RDL (1)	20	N/A	2025/03/21	COR3SOP-00002	EPA 600R-93/116

Remarks:

Bureau Veritas is accredited to ISO/IEC 17025 for specific parameters on scopes of accreditation. Unless otherwise noted, procedures used by Bureau Veritas are based upon recognized Provincial, Federal or US method compendia such as CCME, EPA, APHA or the Quebec Ministry of Environment.

All work recorded herein has been done in accordance with procedures and practices ordinarily exercised by professionals in Bureau Veritas' profession using accepted testing methodologies, quality assurance and quality control procedures (except where otherwise agreed by the client and Bureau Veritas in writing). All data is in statistical control and has met quality control and method performance criteria unless otherwise noted. All method blanks are reported; unless indicated otherwise, associated sample data are not blank corrected. Where applicable, unless otherwise noted, Measurement Uncertainty has not been accounted for when stating conformity to the referenced standard.

Bureau Veritas liability is limited to the actual cost of the requested analyses, unless otherwise agreed in writing. There is no other warranty expressed or implied. Bureau Veritas has been retained to provide analysis of samples provided by the Client using the testing methodology referenced in this report. Interpretation and use of test results are the sole responsibility of the Client and are not within the scope of services provided by Bureau Veritas, unless otherwise agreed in writing. Bureau Veritas is not responsible for the accuracy or any data impacts, that result from the information provided by the customer or their agent.

Solid sample results, except biota, are based on dry weight unless otherwise indicated. Organic analyses are not recovery corrected except for isotope dilution methods.

Results relate to samples tested. When sampling is not conducted by Bureau Veritas, results relate to the supplied samples tested.

This Certificate shall not be reproduced except in full, without the written approval of the laboratory.

Bureau Veritas' Asbestos Laboratory is accredited by NVLAP for bulk asbestos analysis by polarized light microscopy, NVLAP Code 600136-0.

This report may not be reproduced, except in full, without the written approval of Bureau Veritas. This report may not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any other agency of the U.S. Government.

Bureau Veritas' scope of accreditation includes EPA -- 40 CFR Appendix E to Subpart E of Part 763, "Interim Method for the Determination of Asbestos in Bulk Insulation Samples" and EPA-600/R-93/116: "Method for the Determination of Asbestos in Bulk Building Materials".

Reference Method suffix "m" indicates test methods incorporate validated modifications from specific reference methods to improve performance.

* RPDs calculated using raw data. The rounding of final results may result in the apparent difference.

(1) P.O.B. - Percent of Bulk



BUREAU
VERITAS

Your Project #: 352316.001

Site Location: ON

Your C.O.C. #: 1024891

Attention: Pinchin Asbestos Lab

Pinchin Ltd
2360 Meadowpine Blvd
Unit # 2
Mississauga, ON
CANADA L5N 6S2

Report Date: 2025/03/21

Report #: R8507153

Version: 1 - Final

CERTIFICATE OF ANALYSIS

BUREAU VERITAS JOB #: C528244

Received: 2025/03/17, 10:15

When Asbestos data is reported with other data, this report contains data that are not covered by the NVLAP accreditation.

Encryption Key

Please direct all questions regarding this Certificate of Analysis to:

Nilushi Mahathantila, Project Manager
Email: Nilushi.Mahathantila@bureauveritas.com
Phone# (905) 817-5700

=====
This report has been generated and distributed using a secure automated process.

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

Total Cover Pages : 2
Page 2 of 16

Bureau Veritas 6740 Campobello Road, Mississauga, Ontario, L5N 2L8 Tel: (905) 817-5700 Toll-Free: 800-563-6266 Fax: (905) 817-5777 www.bvna.com

Microbiology testing is conducted at 6660 Campobello Rd. Chemistry testing is conducted at 6740 Campobello Rd.



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0072A,Piping,Gasket,Red,Loc:120,Mechanical

Room

Bureau Veritas ID: AOYR63

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous red gasket	Not Detected		Non-Fibrous

S0072B,Piping,Gasket,Red,Loc:120,Mechanical

Room

Bureau Veritas ID: AOYR64

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous red gasket	Not Detected		Non-Fibrous

S0072C,Piping,Gasket,Red,Loc:120,Mechanical

Room

Bureau Veritas ID: AOYR65

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous red gasket	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0073A,Tar,Loc:120,Mechanical Room

Bureau Veritas	AOYR66	Date Analyzed:	2025/03/21
ID:			

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black tar	Not Detected		Non-Fibrous

S0073B,Tar,Loc:120,Mechanical Room

Bureau Veritas	AOYR67	Date Analyzed:	2025/03/21
ID:			

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black tar	Not Detected		Non-Fibrous

S0073C,Tar,Loc:120,Mechanical Room

Bureau Veritas	AOYR68	Date Analyzed:	2025/03/21
ID:			

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black tar	Not Detected		Non-Fibrous

S0074A,Door,Caulking,Grey,Loc:150,Exterior 1967

Era				
Bureau Veritas	AOYR69	Date Analyzed:	2025/03/21	
ID:				

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey caulking	Chrysotile 1%		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0074B,Door,Caulking,Grey,Loc:150,Exterior 1967

Era

Bureau Veritas ID: AOYR70

Date Analyzed: 2025/03/21

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1			N/A		

Comment: Not Analyzed - Positive Stop

S0074C,Door,Caulking,Grey,Loc:150,Exterior 1967

Era

Bureau Veritas ID: AOYR71

Date Analyzed: 2025/03/21

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1			N/A		

Comment: Not Analyzed - Positive Stop

S0075A,Tar,Tar On Canopy Roof,Loc:151,Exterior

1959 Era

Bureau Veritas ID: AOYR72

Date Analyzed: 2025/03/21

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black tar	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0075B,Tar,Tar On Canopy Roof,Loc:151,Exterior

1959 Era

Bureau Veritas ID: AOYR73

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black tar	Not Detected		Non-Fibrous

S0075C,Tar,Tar On Canopy Roof,Loc:151,Exterior

1959 Era

Bureau Veritas ID: AOYR74

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black tar	Not Detected		Non-Fibrous

S0076A,Tar,Tar On Roof Penetration Above Mechanical Room,Loc:151,Exterior 1959 Era

Bureau Veritas ID: AOYR75

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black tar	Not Detected	Cellulose 5%	Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0076B,Tar,Tar On Roof Penetration Above Mechanical Room,Loc:151,Exterior 1959 Era

Bureau Veritas ID: AOYR76

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black tar	Not Detected	Cellulose 5%	Non-Fibrous

S0076C,Tar,Tar On Roof Penetration Above Mechanical Room,Loc:151,Exterior 1959 Era

Bureau Veritas ID: AOYR77

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black tar	Not Detected	Cellulose 5%	Non-Fibrous

S0077A,Floor,Vinyl Floor Tile And Mastic,12x12 Grey With Beige Fleck,Loc:127,Storage / Corridor

Bureau Veritas ID: AOYR78

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	95	Homogeneous grey vinyl floor tile	Not Detected		Non-Fibrous
Layer 2	5	Homogeneous black mastic	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0077B,Floor,Vinyl Floor Tile And Mastic,12x12 Grey With Beige Fleck,Loc:127,Storage / Corridor

Bureau Veritas ID: AOYR79

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	95	Homogeneous grey vinyl floor tile	Not Detected		Non-Fibrous
Layer 2	5	Homogeneous black mastic	Not Detected		Non-Fibrous

S0077C,Floor,Vinyl Floor Tile And Mastic,12x12 Grey With Beige Fleck,Loc:127,Storage / Corridor

Bureau Veritas ID: AOYR80

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	95	Homogeneous grey vinyl floor tile	Not Detected		Non-Fibrous
Layer 2	5	Homogeneous black mastic	Not Detected		Non-Fibrous

S0078A,Wall,Vermiculite,Loc:103,Classroom

Bureau Veritas ID: AOYR81

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous grey debris	Not Detected	Cellulose 20%	Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0078B, Wall, Vermiculite, Loc:104, Classroom /

Storage

Bureau Veritas ID: AOYR82

Date Analyzed: 2025/03/21

	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey/brown vermiculite	Libby Amphibole Present%		Non-Fibrous
Comment:		Vermiculite originating from Libby, Montana is known to be contaminated with regulated (tremolite and actinolite) and unregulated (primarily winchite and richterite) asbestos fibers. TEM analysis is recommended for a more accurate characterization of			

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)

Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

TEST SUMMARY

Bureau Veritas ID: AOYR63 **Collected:** 2025/03/10
Sample ID: S0072A,Piping,Gasket,Red,Loc:120,Mechanical Room **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR64 **Collected:** 2025/03/10
Sample ID: S0072B,Piping,Gasket,Red,Loc:120,Mechanical Room **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR65 **Collected:** 2025/03/10
Sample ID: S0072C,Piping,Gasket,Red,Loc:120,Mechanical Room **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR66 **Collected:** 2025/03/10
Sample ID: S0073A,Tar,Loc:120,Mechanical Room **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR67 **Collected:** 2025/03/10
Sample ID: S0073B,Tar,Loc:120,Mechanical Room **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR68 **Collected:** 2025/03/10
Sample ID: S0073C,Tar,Loc:120,Mechanical Room **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR69 **Collected:** 2025/03/10
Sample ID: S0074A,Door,Caulking,Grey,Loc:150,Exterior 1967 Era **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

TEST SUMMARY

Bureau Veritas ID: AOYR69 Dup
Sample ID: S0074A,Door,Caulking,Grey,Loc:150,Exterior 1967 Era
Matrix: Solid

Collected: 2025/03/10
Shipped:
Received: 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR70
Sample ID: S0074B,Door,Caulking,Grey,Loc:150,Exterior 1967 Era
Matrix: Solid

Collected: 2025/03/10
Shipped:
Received: 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR71
Sample ID: S0074C,Door,Caulking,Grey,Loc:150,Exterior 1967 Era
Matrix: Solid

Collected: 2025/03/10
Shipped:
Received: 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR72
Sample ID: S0075A,Tar,Tar On Canopy Roof,Loc:151,Exterior 1959 Era
Matrix: Solid

Collected: 2025/03/10
Shipped:
Received: 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR73
Sample ID: S0075B,Tar,Tar On Canopy Roof,Loc:151,Exterior 1959 Era
Matrix: Solid

Collected: 2025/03/10
Shipped:
Received: 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR74
Sample ID: S0075C,Tar,Tar On Canopy Roof,Loc:151,Exterior 1959 Era
Matrix: Solid

Collected: 2025/03/10
Shipped:
Received: 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR74 Dup
Sample ID: S0075C,Tar,Tar On Canopy Roof,Loc:151,Exterior 1959 Era
Matrix: Solid

Collected: 2025/03/10
Shipped:
Received: 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

TEST SUMMARY

Bureau Veritas ID: AOYR75 **Collected:** 2025/03/10
Sample ID: S0076A,Tar,Tar On Roof Penetration Above Mechanical Room,Loc:151,Exterior 1959 Era **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR76 **Collected:** 2025/03/10
Sample ID: S0076B,Tar,Tar On Roof Penetration Above Mechanical Room,Loc:151,Exterior 1959 Era **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR77 **Collected:** 2025/03/10
Sample ID: S0076C,Tar,Tar On Roof Penetration Above Mechanical Room,Loc:151,Exterior 1959 Era **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR78 **Collected:** 2025/03/10
Sample ID: S0077A,Floor,Vinyl Floor Tile And Mastic,12x12 Grey With Beige Fleck,Loc:127,Storage / Contaminated **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR79 **Collected:** 2025/03/10
Sample ID: S0077B,Floor,Vinyl Floor Tile And Mastic,12x12 Grey With Beige Fleck,Loc:127,Storage / Contaminated **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR80 **Collected:** 2025/03/10
Sample ID: S0077C,Floor,Vinyl Floor Tile And Mastic,12x12 Grey With Beige Fleck,Loc:127,Storage / Contaminated **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos

Bureau Veritas ID: AOYR81 **Collected:** 2025/03/10
Sample ID: S0078A,Wall,Vermiculite,Loc:103,Classroom **Shipped:**
Matrix: Solid **Received:** 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

TEST SUMMARY

Bureau Veritas ID: AOYR82

Sample ID: S0078B,Wall,Vermiculite,Loc:104,Classroom / Storage

Matrix: Solid

Collected: 2025/03/10

Shipped:

Received: 2025/03/17

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	9895329	N/A		Jon Delos Santos



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

GENERAL COMMENTS

Results relate only to the items tested.



BUREAU
VERITAS

Bureau Veritas Job #: C528244

Report Date: 2025/03/21

Pinchin Ltd

Client Project #: 352316.001

Site Location: ON

Sampler Initials: BW

VALIDATION SIGNATURE PAGE

The analytical data and all QC contained in this report were reviewed and validated by:

Dina Yousif, Analyst 2

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

C528244
JOB #
2025/03/17 10:15

CLIENT NAME:

Maxxam Analytics
CAM FCD-01053/2
Page 1 of 1

T1024891

Internal Sample Receipt Form

Sample Identification		Date Sampled	Time Sampled	Matrix	# of Bottles	Comments					
1						3523/6 '001					
2											
3											
4											
5											
6											
7											
8											
9											
10											
11											
12											
13											
14											
15											
Received by (Signature & Print):		Date	Time	Cooler ID	Temperature	Custody seal Present	Custody Seal Intact	Ice Present			
		2025/03/17	10:15			YES	NO	YES	NO	YES	NO



NONT-2025-03-3224

APPENDIX II-B
Lead Analytical Certificates



BUREAU
VERITAS

Your Project #: 352316.001

Site Location: KILBRIDE

Your C.O.C. #: N/A

Attention: Ben Weir

Pinchin Ltd
151 York Boulevard
Suite 200
Hamilton, ON
CANADA L8R 3M2

Report Date: 2025/03/04

Report #: R8496863

Version: 1 - Final

CERTIFICATE OF ANALYSIS

BUREAU VERITAS JOB #: C521263

Received: 2025/02/27, 10:55

Sample Matrix: Paint
Samples Received: 14

Analyses	Quantity	Date Extracted	Date Analyzed	Laboratory Method	Analytical Method
		1	2025/03/03	2025/03/03	CAM SOP-00408
Metals in Paint	13	2025/03/04	2025/03/04	CAM SOP-00408	EPA 6010D m

Remarks:

Bureau Veritas is accredited to ISO/IEC 17025 for specific parameters on scopes of accreditation. Unless otherwise noted, procedures used by Bureau Veritas are based upon recognized Provincial, Federal or US method compendia such as CCME, EPA, APHA or the Quebec Ministry of Environment.

All work recorded herein has been done in accordance with procedures and practices ordinarily exercised by professionals in Bureau Veritas' profession using accepted testing methodologies, quality assurance and quality control procedures (except where otherwise agreed by the client and Bureau Veritas in writing). All data is in statistical control and has met quality control and method performance criteria unless otherwise noted. All method blanks are reported; unless indicated otherwise, associated sample data are not blank corrected. Where applicable, unless otherwise noted, Measurement Uncertainty has not been accounted for when stating conformity to the referenced standard.

Bureau Veritas liability is limited to the actual cost of the requested analyses, unless otherwise agreed in writing. There is no other warranty expressed or implied. Bureau Veritas has been retained to provide analysis of samples provided by the Client using the testing methodology referenced in this report. Interpretation and use of test results are the sole responsibility of the Client and are not within the scope of services provided by Bureau Veritas, unless otherwise agreed in writing. Bureau Veritas is not responsible for the accuracy or any data impacts, that result from the information provided by the customer or their agent.

Solid sample results, except biota, are based on dry weight unless otherwise indicated. Organic analyses are not recovery corrected except for isotope dilution methods.

Results relate to samples tested. When sampling is not conducted by Bureau Veritas, results relate to the supplied samples tested.

This Certificate shall not be reproduced except in full, without the written approval of the laboratory.

Reference Method suffix "m" indicates test methods incorporate validated modifications from specific reference methods to improve performance.

* RPDs calculated using raw data. The rounding of final results may result in the apparent difference.



BUREAU
VERITAS

Your Project #: 352316.001

Site Location: KILBRIDE

Your C.O.C. #: N/A

Attention: Ben Weir

Pinchin Ltd
151 York Boulevard
Suite 200
Hamilton, ON
CANADA L8R 3M2

Report Date: 2025/03/04

Report #: R8496863

Version: 1 - Final

CERTIFICATE OF ANALYSIS

BUREAU VERITAS JOB #: C521263

Received: 2025/02/27, 10:55

Encryption Key

Please direct all questions regarding this Certificate of Analysis to:

Nilushi Mahathantila, Project Manager

Email: Nilushi.Mahathantila@bureauveritas.com

Phone# (905) 817-5700

=====
This report has been generated and distributed using a secure automated process.

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports.

For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

Total Cover Pages : 2
Page 2 of 8



BUREAU
VERITAS

Bureau Veritas Job #: C521263

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: KILBRIDE

Sampler Initials: BW

ELEMENTS BY ATOMIC SPECTROSCOPY (PAINT)

Bureau Veritas ID		AOLJ95		AOLJ96		AOLJ97		
Sampling Date		2025/02/18		2025/02/18		2025/02/18		
COC Number		N/A		N/A		N/A		
	UNITS	L0001, FLOOR, CONCRETE (POURED), GREY, LOC: 120, MECHANICAL ROOM	RDL	L0002, WALL, CONCRETE (PRECAST), LIGHT GREEN, LOC: 120, MECHANICAL ROOM	RDL	L0003, PIPING, METAL, BLUE, LOC: 120, MECHANICAL ROOM	RDL	QC Batch

Metals

Lead (Pb)	%	0.40	0.00053	0.29	0.00041	0.23	0.0013	9884463
-----------	---	------	---------	------	---------	------	--------	---------

RDL = Reportable Detection Limit

QC Batch = Quality Control Batch

Bureau Veritas ID		AOLJ98		AOLJ99		AOLK00		
Sampling Date		2025/02/18		2025/02/18		2025/02/18		
COC Number		N/A		N/A		N/A		
	UNITS	L0004, PIPING, METAL, YELLOW, LOC: 120, MECHANICAL ROOM	RDL	L0005, WALL, CONCRETE (PRECAST), LIGHT BEIGE, LOC: 105, CLASSROOM/STORAG E	RDL	L0006, WALL, CONCRETE (PRECAST), LIGHT PINK, LOC: 114, CLASSROOM	RDL	QC Batch

Metals

Lead (Pb)	%	0.011	0.00085	0.0043	0.00033	0.14	0.00031	9884617
-----------	---	-------	---------	--------	---------	------	---------	---------

RDL = Reportable Detection Limit

QC Batch = Quality Control Batch

Bureau Veritas ID		AOLK01		AOLK02			
Sampling Date		2025/02/18		2025/02/18			
COC Number		N/A		N/A			
	UNITS	L0007, WALL, CONCRETE (PRECAST), CREAM, LOC: 126, OFFICE/WASHROOM	RDL	L0008, WALL, CONCRETE (PRECAST), LIGHT CREAM, LOC:112, CLASSROOM	RDL	QC Batch	
Metals							
Lead (Pb)	%	0.13	0.00041	0.15	0.00038	0.00038	9884617
RDL = Reportable Detection Limit							
QC Batch = Quality Control Batch							



BUREAU
VERITAS

Bureau Veritas Job #: C521263

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: KILBRIDE

Sampler Initials: BW

ELEMENTS BY ATOMIC SPECTROSCOPY (PAINT)

Bureau Veritas ID		AOLK03	AOLK03			AOLK04		
Sampling Date		2025/02/18	2025/02/18			2025/02/18		
COC Number		N/A	N/A			N/A		
	UNITS	L0009, CEILING, DRYWALL AND JOINT COMPOUND, BEIGE, LOC:145, CORRIDOR Lab-Dup	L0009, CEILING, DRYWALL AND JOINT COMPOUND, BEIGE, LOC:145, CORRIDOR Lab-Dup	RDL	QC Batch	L0010, OTHER, METAL, BLUE, DOOR 1, LOC: 150, EXTERIOR	RDL	QC Batch

Metals

Lead (Pb)	%	0.0024	0.0021	0.00010	9884463	0.0018	0.00044	9884617
-----------	---	--------	--------	---------	---------	--------	---------	---------

RDL = Reportable Detection Limit

QC Batch = Quality Control Batch

Lab-Dup = Laboratory Initiated Duplicate

Bureau Veritas ID		AOLK05		AOLK06		
Sampling Date		2025/02/18		2025/02/18		
COC Number		N/A		N/A		
	UNITS	L0011, OTHER, WOOD, WHITE, CANOPY BEAM, LOC: 150, EXTERIOR	RDL	L0012, OTHER, WOOD, BROWN, CANOPY DECK, LOC: 150, EXTERIOR	RDL	QC Batch

Metals

Lead (Pb)	%	0.97	0.0010	0.26	0.0012	9884617
-----------	---	------	--------	------	--------	---------

RDL = Reportable Detection Limit

QC Batch = Quality Control Batch

Bureau Veritas ID		AOLK07	AOLK07			AOLK08		
Sampling Date		2025/02/18	2025/02/18			2025/02/18		
COC Number		N/A	N/A			N/A		
	UNITS	L0013, CEILING, DRYWALL (NO COMPOUND), WHITE ON SOFFIT, DOOR 11, LOC:150, EXTERIOR Lab-Dup	L0013, CEILING, DRYWALL (NO COMPOUND), WHITE ON SOFFIT, DOOR 11, LOC:150, EXTERIOR Lab-Dup	RDL	QC Batch	L0014, WALL, CONCRETE BLOCK, CREAM/BLUE, LOC: 140, CORRIDOR	RDL	QC Batch

Metals

Lead (Pb)	%	0.0021	0.0020	0.00010	9883862	0.0024	0.00086	9884617
-----------	---	--------	--------	---------	---------	--------	---------	---------

RDL = Reportable Detection Limit

QC Batch = Quality Control Batch

Lab-Dup = Laboratory Initiated Duplicate



BUREAU
VERITAS

Bureau Veritas Job #: C521263

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: KILBRIDE

Sampler Initials: BW

GENERAL COMMENTS

Sample AOLJ95 [L0001, FLOOR, CONCRETE (POURED), GREY, LOC: 120, MECHANICAL ROOM] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample AOLJ96 [L0002, WALL, CONCRETE (PRECAST), LIGHT GREEN, LOC: 120, MECHANICAL ROOM] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample AOLJ97 [L0003, PIPING, METAL, BLUE, LOC: 120, MECHANICAL ROOM] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample AOLJ98 [L0004, PIPING, METAL, YELLOW, LOC: 120, MECHANICAL ROOM] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample AOLJ99 [L0005, WALL, CONCRETE (PRECAST), LIGHT BEIGE, LOC: 105, CLASSROOM/STORAGE] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample AOLK00 [L0006, WALL, CONCRETE (PRECAST), LIGHT PINK, LOC: 114, CLASSROOM] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample AOLK01 [L0007, WALL, CONCRETE (PRECAST), CREAM, LOC: 126, OFFICE/WASHROOM] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample AOLK02 [L0008, WALL, CONCRETE (PRECAST), LIGHT CREAM, LOC: 112, CLASSROOM] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample AOLK04 [L0010, OTHER, METAL, BLUE, DOOR 1, LOC: 150, EXTERIOR] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample AOLK05 [L0011, OTHER, WOOD, WHITE, CANOPY BEAM, LOC: 150, EXTERIOR] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample AOLK06 [L0012, OTHER, WOOD, BROWN, CANOPY DECK, LOC: 150, EXTERIOR] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Sample AOLK08 [L0014, WALL, CONCRETE BLOCK, CREAM/BLUE, LOC: 140, CORRIDOR] : Metals Analysis: Due to limited amount of sample available for analysis, a smaller than usual portion of the sample was used. Detection limits were adjusted accordingly.

Results relate only to the items tested.



BUREAU
VERITAS

Bureau Veritas Job #: C521263

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: KILBRIDE

Sampler Initials: BW

QUALITY ASSURANCE REPORT

QA/QC	Batch	Init	QC Type	Parameter	Date Analyzed	Value	Recovery	UNITS	QC Limits
9883862	TLG		Matrix Spike [AOLK07-01]	Lead (Pb)	2025/03/03	97	%	75 - 125	
9883862	TLG		QC Standard	Lead (Pb)	2025/03/03	105	%	75 - 125	
9883862	TLG		Method Blank	Lead (Pb)	2025/03/03	<0.00010	%		
9883862	TLG		RPD [AOLK07-01]	Lead (Pb)	2025/03/03	3.1	%	35	
9884463	GR1		Matrix Spike [AOLK03-01]	Lead (Pb)	2025/03/04	88	%	75 - 125	
9884463	GR1		QC Standard	Lead (Pb)	2025/03/04	103	%	75 - 125	
9884463	GR1		Method Blank	Lead (Pb)	2025/03/04	<0.00010	%		
9884463	GR1		RPD [AOLK03-01]	Lead (Pb)	2025/03/04	11	%	35	
9884617	GR1		Matrix Spike	Lead (Pb)	2025/03/04	79	%	75 - 125	
9884617	GR1		QC Standard	Lead (Pb)	2025/03/04	102	%	75 - 125	
9884617	GR1		Method Blank	Lead (Pb)	2025/03/04	<0.00010	%		
9884617	GR1	RPD		Lead (Pb)	2025/03/04	6.0	%	35	

Duplicate: Paired analysis of a separate portion of the same sample. Used to evaluate the variance in the measurement.

Matrix Spike: A sample to which a known amount of the analyte of interest has been added. Used to evaluate sample matrix interference.

QC Standard: A sample of known concentration prepared by an external agency under stringent conditions. Used as an independent check of method accuracy.

Method Blank: A blank matrix containing all reagents used in the analytical procedure. Used to identify laboratory contamination.



BUREAU
VERITAS

Bureau Veritas Job #: C521263

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: KILBRIDE

Sampler Initials: BW

VALIDATION SIGNATURE PAGE

The analytical data and all QC contained in this report were reviewed and validated by:

Cristina Carriere

Cristina Carriere, Senior Scientific Specialist

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.



6740 Campobello Road, Mississauga, Ontario L5N 2L8
Phone: 905-817-5700 Fax: 905-817-5779 Toll Free: 800-563-6266
CAM FCD-01191/6

CHAIN OF CUSTODY RECORD

Page ____ of ____

Invoice Information		Report Information (if differs from invoice)		Project Information (where applicable)		Turnaround Time (TAT) Required		
Company Name: Pinchin Ltd.		Company Name: _____		Quotation #: _____		<input checked="" type="checkbox"/> Regular TAT (5-7 days) Most analyses		
Contact Name: Ben Weir / Emily Balfour / Jessica Cozzitorto		Contact Name: _____		P.O. #/ AFER: _____		PLEASE PROVIDE ADVANCE NOTICE FOR RUSH PROJECTS		
Address: _____		Address: _____		Project #: 352316.001		Rush TAT (Surcharges will be applied)		
Phone: _____	Fax: _____	Phone: _____	Fax: _____	Site Location: Kilbride		<input type="checkbox"/> 1 Day	<input type="checkbox"/> 2 Days	<input type="checkbox"/> 3-4 Days
Email: bweir@pinchin.com / ebalfour@pinchin.com / jcozzitorto@pinchin.com		Email: _____		Site #: _____		Date Required: 03-Mar-25		
MOE REGULATED DRINKING WATER OR WATER INTENDED FOR HUMAN CONSUMPTION MUST BE SUBMITTED ON THE BUREAU VERITAS DRINKING WATER CHAIN OF CUSTODY								
Regulation 153	Other Regulations		Analysis Requested		LABORATORY USE ONLY			
<input type="checkbox"/> Table 1 <input type="checkbox"/> Res/Park <input type="checkbox"/> Med/ Fine <input type="checkbox"/> Table 2 <input type="checkbox"/> Ind/Comm <input type="checkbox"/> Coarse <input type="checkbox"/> Table 3 <input type="checkbox"/> Agri/ Other <input type="checkbox"/> Table _____	<input type="checkbox"/> CCME <input type="checkbox"/> Sanitary Sewer Bylaw <input type="checkbox"/> MISA <input type="checkbox"/> Storm Sewer Bylaw <input type="checkbox"/> PWQO <input type="checkbox"/> Region _____ <input type="checkbox"/> Other (Specify) _____ <input type="checkbox"/> REG 558 (MIN. 3 DAY TAT REQUIRED) <input type="checkbox"/> REG 406 Table _____		# OF CONTAINERS SUBMITTED FIELD FILTERED (CIRCLE) Metals / Hg / Cr VI BTEX / PCP / F1 PIC / F2 - F4 VOCs REG 558 METALS & INORGANICS REG 406 METALS REG 153 (PCP) METALS (Hg, Cr VI, PCP) Metals, HgNS - B Lead (Pb) in Paints PCBs		CUSTODY SEAL Y / N Present <input checked="" type="checkbox"/> Intact <input type="checkbox"/> COOLER TEMPERATURES <i>N/N</i> HOLD DO NOT ANALYZE COOLING MEDIA PRESENT: Y / <input type="checkbox"/> COMMENTS			
Include Criteria on Certificate of Analysis: Y / N								
SAMPLES MUST BE KEPT COOL (< 10 °C) FROM TIME OF SAMPLING UNTIL DELIVERY TO BUREAU VERITAS								
SAMPLE IDENTIFICATION	DATE SAMPLED (YYYY/MM/DD)	TIME SAMPLED (HH:MM)	MATRIX					
L0001, Floor, Concrete (poured), Grey,Loc:120,Mechanical Room	2025/02/18	PM	BULK					
L0002, Wall, Concrete (precast), Light Green,Loc:120,Mechanical Room	2025/02/18	PM	BULK					
L0003, Piping, Metal, Blue,Loc:120,Mechanical Room	2025/02/18	PM	BULK					
L0004, Piping, Metal, Yellow,Loc:120,Mechanical Room	2025/02/18	PM	BULK					
L0005, Wall, Concrete (precast), Light Beige,Loc:105,Classroom / Storage	2025/02/18	PM	BULK					
L0006, Wall, Concrete (precast), Light Pink,Loc:114,Classroom	2025/02/18	PM	BULK					
L0007, Wall, Concrete (precast), Cream,Loc:126,Office / Washroom	2025/02/18	PM	BULK					
L0008, Wall, Concrete (precast), Light Cream,Loc:112,Classroom	2025/02/18	PM	BULK					
L0009, Ceiling, Drywall and joint compound, Beige,Loc:145,Corridor	2025/02/18	PM	BULK					
L0010, Other, Metal, Blue, Door 1,Loc:150,Exterior	2025/02/18	PM	BULK					
L0011, Other, Wood, White, Canopy Beam,Loc:150,Exterior	2025/02/18	PM	BULK					
L0012, Other, Wood, Brown, Canopy Deck,Loc:150,Exterior	2025/02/18	PM	BULK					
L0013, Ceiling, Drywall (no compound), White On Soffit, Door 11,Loc:150,Exterior	2025/02/18	PM	BULK					
L0014, Wall, Concrete Block, Cream/blue,Loc:140,Corridor	2025/02/18	PM	BULK					
RELINQUISHED BY: [Signature/Print]	DATE: (YYYY/MM/DD)	TIME: (HH:MM)	RECEIVED BY: [Signature/Print]	DATE: (YYYY/MM/DD)	TIME: (HH:MM)	BV JOB #		
Emily Balfour	2025/02/24	2:00PM	<i>Sugar Samah</i>	2025/02/27	10:55			

Unless otherwise agreed to in writing, work submitted on this Chain of Custody is subject to Bureau Veritas' standard Terms and Conditions. Signing of this Chain of Custody document is acknowledgment and acceptance of our terms available at <https://www.bvna.com/coc-terms-and-conditions>



NONT-2025-02-4599



BUREAU
VERITAS

Your Project #: 352316.001
Your C.O.C. #: N/A

Attention: Jessica Cozzitorto

Pinchin Ltd
151 York Boulevard
Suite 200
Hamilton, ON
CANADA L8R 3M2

Report Date: 2025/03/20

Report #: R8506293

Version: 1 - Final

CERTIFICATE OF ANALYSIS

BUREAU VERITAS JOB #: C528304

Received: 2025/03/17, 10:15

Sample Matrix: Paint
Samples Received: 2

Analyses	Quantity	Date Extracted	Date Analyzed	Laboratory Method	Analytical Method
Metals in Paint	2	2025/03/20	2025/03/20	CAM SOP-00408	EPA 6010D m

Remarks:

Bureau Veritas is accredited to ISO/IEC 17025 for specific parameters on scopes of accreditation. Unless otherwise noted, procedures used by Bureau Veritas are based upon recognized Provincial, Federal or US method compendia such as CCME, EPA, APHA or the Quebec Ministry of Environment.

All work recorded herein has been done in accordance with procedures and practices ordinarily exercised by professionals in Bureau Veritas' profession using accepted testing methodologies, quality assurance and quality control procedures (except where otherwise agreed by the client and Bureau Veritas in writing). All data is in statistical control and has met quality control and method performance criteria unless otherwise noted. All method blanks are reported; unless indicated otherwise, associated sample data are not blank corrected. Where applicable, unless otherwise noted, Measurement Uncertainty has not been accounted for when stating conformity to the referenced standard.

Bureau Veritas liability is limited to the actual cost of the requested analyses, unless otherwise agreed in writing. There is no other warranty expressed or implied. Bureau Veritas has been retained to provide analysis of samples provided by the Client using the testing methodology referenced in this report. Interpretation and use of test results are the sole responsibility of the Client and are not within the scope of services provided by Bureau Veritas, unless otherwise agreed in writing. Bureau Veritas is not responsible for the accuracy or any data impacts, that result from the information provided by the customer or their agent.

Solid sample results, except biota, are based on dry weight unless otherwise indicated. Organic analyses are not recovery corrected except for isotope dilution methods.

Results relate to samples tested. When sampling is not conducted by Bureau Veritas, results relate to the supplied samples tested.

This Certificate shall not be reproduced except in full, without the written approval of the laboratory.

Reference Method suffix "m" indicates test methods incorporate validated modifications from specific reference methods to improve performance.

* RPDs calculated using raw data. The rounding of final results may result in the apparent difference.



BUREAU
VERITAS

Your Project #: 352316.001
Your C.O.C. #: N/A

Attention: Jessica Cozzitorto

Pinchin Ltd
151 York Boulevard
Suite 200
Hamilton, ON
CANADA L8R 3M2

Report Date: 2025/03/20

Report #: R8506293

Version: 1 - Final

CERTIFICATE OF ANALYSIS

BUREAU VERITAS JOB #: C528304

Received: 2025/03/17, 10:15

Encryption Key

Please direct all questions regarding this Certificate of Analysis to:

Nilushi Mahathantila, Project Manager
Email: Nilushi.Mahathantila@bureauveritas.com
Phone# (905) 817-5700

=====
This report has been generated and distributed using a secure automated process.

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

Total Cover Pages : 2
Page 2 of 7



BUREAU
VERITAS

Bureau Veritas Job #: C528304

Report Date: 2025/03/20

Pinchin Ltd

Client Project #: 352316.001

Sampler Initials: BW

ELEMENTS BY ATOMIC SPECTROSCOPY (PAINT)

Bureau Veritas ID		AOYU01	AOYU02		
Sampling Date		2025/03/10	2025/03/10		
COC Number		N/A	N/A		
	UNITS	L0015,MECHANICAL EQUIPMENT,METAL, WHITE ON METAL CUSHI	L0016,WALL,CONCRETE(PRECAST),CREAM ON BLOCK,LOC:143,CON	RDL	QC Batch
Metals					
Lead (Pb)	%	0.052	0.00043	0.00010	9894534
RDL = Reportable Detection Limit					
QC Batch = Quality Control Batch					



BUREAU
VERITAS

Bureau Veritas Job #: C528304

Report Date: 2025/03/20

Pinchin Ltd

Client Project #: 352316.001

Sampler Initials: BW

GENERAL COMMENTS

Results relate only to the items tested.



BUREAU
VERITAS

Bureau Veritas Job #: C528304

Report Date: 2025/03/20

Pinchin Ltd

Client Project #: 352316.001

Sampler Initials: BW

QUALITY ASSURANCE REPORT

QA/QC		Parameter	Date Analyzed	Value	Recovery	UNITS	QC Limits
Batch	Init	QC Type					
9894534	MEN	Matrix Spike	Lead (Pb)	2025/03/20	109	%	75 - 125
9894534	MEN	QC Standard	Lead (Pb)	2025/03/20	102	%	75 - 125
9894534	MEN	Method Blank	Lead (Pb)	2025/03/20	<0.00010	%	
9894534	MEN	RPD	Lead (Pb)	2025/03/20	6.7	%	35

Duplicate: Paired analysis of a separate portion of the same sample. Used to evaluate the variance in the measurement.

Matrix Spike: A sample to which a known amount of the analyte of interest has been added. Used to evaluate sample matrix interference.

QC Standard: A sample of known concentration prepared by an external agency under stringent conditions. Used as an independent check of method accuracy.

Method Blank: A blank matrix containing all reagents used in the analytical procedure. Used to identify laboratory contamination.



BUREAU
VERITAS

Bureau Veritas Job #: C528304

Report Date: 2025/03/20

Pinchin Ltd

Client Project #: 352316.001

Sampler Initials: BW

VALIDATION SIGNATURE PAGE

The analytical data and all QC contained in this report were reviewed and validated by:

Louise Harding, Scientific Specialist

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.



6740 Campobello Road, Mississauga, Ontario L5N 2L8

Phone: 905-817-5700 Fax: 905-817-5779 Toll Free: 800-563-6266

CAM FCD-01191/6

CHAIN OF CUSTODY RECORD

Page _____ of _____

Invoice Information		Report Information (if differs from invoice)		Project Information (where applicable)		Turnaround Time (TAT) Required	
Company Name: Pinchin Ltd. Contact Name: Ben Weir Jessica Cozzitorto Emily Balfour Address: Phone: _____ Fax: _____ Email: bweir@pinchin.com jcozzitorto@Pinchin.com ebalfour@P		Company Name: _____ Contact Name: _____ Address: _____ Phone: _____ Fax: _____ Email: _____		Quotation #: _____ P.O. #/ AFE #: _____ Project #: 352316.001 Site Location: _____ Site #: _____ Site Location Province: _____ ON Sampled By: Ben Weir		<input checked="" type="checkbox"/> Regular TAT (5-7 days) Most analyses PLEASE PROVIDE ADVANCE NOTICE FOR RUSH PROJECTS Rush TAT (Surcharges will be applied) <input type="checkbox"/> 1 Day <input type="checkbox"/> 2 Days <input type="checkbox"/> 3-4 Days	
MOE REGULATED DRINKING WATER OR WATER INTENDED FOR HUMAN CONSUMPTION MUST BE SUBMITTED ON THE BUREAU VERITAS DRINKING WATER CHAIN OF CUSTODY							
Regulation 153 <input type="checkbox"/> Table 1 <input type="checkbox"/> Res/Park <input type="checkbox"/> Med/ Fine <input type="checkbox"/> Table 2 <input type="checkbox"/> Ind/Comm <input type="checkbox"/> Coarse <input type="checkbox"/> Table 3 <input type="checkbox"/> Agri/ Other <input type="checkbox"/> Table _____ FOR RSC (PLEASE CIRCLE) <input type="checkbox"/> Y / <input type="checkbox"/> N		Other Regulations <input type="checkbox"/> CCME <input type="checkbox"/> Sanitary Sewer Bylaw <input type="checkbox"/> MISA <input type="checkbox"/> Storm Sewer Bylaw <input type="checkbox"/> PWQO Region _____ <input type="checkbox"/> Other (Specify) _____ <input type="checkbox"/> REG 558 (MIN. 3 DAY TAT REQUIRED) <input type="checkbox"/> REG 406 Table _____		Analysis Requested # OF CONTAINERS SUBMITTED FIELD FILTERED (CIRCLE) Metals / Hg / Cr / V / Pb / C / V / BTEX / PHC F1 PHCs F2 - F4 VOCs REG 153 METALS & INORGANICS REG 153 ICPOMS METALS REG 153 METALS (Hg, Cr, V, ICPOMS Metals, Hg - B) Lead (Pb) in Paints PCBs HOLD: DO NOT ANALYZE		LABORATORY USE ONLY CUSTODY SEAL Y / <input type="checkbox"/> N COOLER TEMPERATURES Present <input type="checkbox"/> Intact <i>w w</i>	
Include Criteria on Certificate of Analysis: <input type="checkbox"/> Y / <input type="checkbox"/> N							
SAMPLES MUST BE KEPT COOL (< 10 °C) FROM TIME OF SAMPLING UNTIL DELIVERY TO BUREAU VERITAS							
SAMPLE IDENTIFICATION		DATE SAMPLED (YYYY/MM/DD)	TIME SAMPLED (HH:MM)	MATRIX			
L0015, Mechanical Equipment, Metal, White On Metal Cushi		2025-03-10		BULK			
L0016, Wall, Concrete (precast), Cream On Block, Loc:143, Co		2025-03-10		BULK			
RELINQUISHED BY: (Signature/Print)		DATE: (YYYY/MM/DD)	TIME: (HH:MM)	RECEIVED BY: (Signature/Print)	DATE: (YYYY/MM/DD)	TIME: (HH:MM)	BV JOB #
Ben Weir		2024-03-14		<i>Ben Weir</i>	<i>105</i>		

Unless otherwise agreed to in writing, work submitted on this Chain of Custody is subject to Bureau Veritas' standard Terms and Conditions. Signing of this Chain of Custody document is acknowledgment and acceptance of our terms available at <https://www.bvna.com/coc-terms-and-conditions>



NONT-2025-03-3235

APPENDIX II-C
PCB Analytical Certificates



BUREAU
VERITAS

Your Project #: 352316.001

Site Location: KILBRIDE

Your C.O.C. #: N/A

Attention: Ben Weir

Pinchin Ltd
151 York Boulevard
Suite 200
Hamilton, ON
CANADA L8R 3M2

Report Date: 2025/03/04

Report #: R8496846

Version: 1 - Final

CERTIFICATE OF ANALYSIS

BUREAU VERITAS JOB #: C521264

Received: 2025/02/27, 10:55

Sample Matrix: Solid
Samples Received: 4

Analyses	Quantity	Date Extracted	Date Analyzed	Laboratory Method	Analytical Method
		3	2025/03/01	2025/03/03	CAM SOP-00309
Polychlorinated Biphenyl in Solids (1)	1	2025/03/01	2025/03/04	CAM SOP-00309	EPA 8082A m

Remarks:

Bureau Veritas is accredited to ISO/IEC 17025 for specific parameters on scopes of accreditation. Unless otherwise noted, procedures used by Bureau Veritas are based upon recognized Provincial, Federal or US method compendia such as CCME, EPA, APHA or the Quebec Ministry of Environment.

All work recorded herein has been done in accordance with procedures and practices ordinarily exercised by professionals in Bureau Veritas' profession using accepted testing methodologies, quality assurance and quality control procedures (except where otherwise agreed by the client and Bureau Veritas in writing). All data is in statistical control and has met quality control and method performance criteria unless otherwise noted. All method blanks are reported; unless indicated otherwise, associated sample data are not blank corrected. Where applicable, unless otherwise noted, Measurement Uncertainty has not been accounted for when stating conformity to the referenced standard.

Bureau Veritas liability is limited to the actual cost of the requested analyses, unless otherwise agreed in writing. There is no other warranty expressed or implied. Bureau Veritas has been retained to provide analysis of samples provided by the Client using the testing methodology referenced in this report. Interpretation and use of test results are the sole responsibility of the Client and are not within the scope of services provided by Bureau Veritas, unless otherwise agreed in writing. Bureau Veritas is not responsible for the accuracy or any data impacts, that result from the information provided by the customer or their agent.

Solid sample results, except biota, are based on dry weight unless otherwise indicated. Organic analyses are not recovery corrected except for isotope dilution methods.

Results relate to samples tested. When sampling is not conducted by Bureau Veritas, results relate to the supplied samples tested.

This Certificate shall not be reproduced except in full, without the written approval of the laboratory.

Reference Method suffix "m" indicates test methods incorporate validated modifications from specific reference methods to improve performance.

* RPDs calculated using raw data. The rounding of final results may result in the apparent difference.

(1) Analysis was conducted according to Bureau Veritas method CAM SOP-00309 and modified where applicable based on the sample matrix. This test is not Standards Council of Canada accredited for this matrix.



BUREAU
VERITAS

Your Project #: 352316.001

Site Location: KILBRIDE

Your C.O.C. #: N/A

Attention: Ben Weir

Pinchin Ltd
151 York Boulevard
Suite 200
Hamilton, ON
CANADA L8R 3M2

Report Date: 2025/03/04

Report #: R8496846

Version: 1 - Final

CERTIFICATE OF ANALYSIS

BUREAU VERITAS JOB #: C521264

Received: 2025/02/27, 10:55

Encryption Key

Please direct all questions regarding this Certificate of Analysis to:

Nilushi Mahathantila, Project Manager

Email: Nilushi.Mahathantila@bureauveritas.com

Phone# (905) 817-5700

=====
This report has been generated and distributed using a secure automated process.

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports.

For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

Total Cover Pages : 2
Page 2 of 8



BUREAU
VERITAS

Bureau Veritas Job #: C521264

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: KILBRIDE

Sampler Initials: BW

POLYCHLORINATED BIPHENYLS BY GC-ECD (SOLID)

Bureau Veritas ID		AOLK09		AOLK10		AOLK11		
Sampling Date		2025/02/18		2025/02/18		2025/02/18		
COC Number		N/A		N/A		N/A		
	UNITS	P0001, COMPOSITE, 1967, LOC:111, CLASSROOM	RDL	P0002, COMPOSITE, 1967, LOC:150, EXTERIOR	RDL	P0003, COMPOSITE, 1959, LOC:150, EXTERIOR	RDL	QC Batch
PCBs								
Aroclor 1262	ug/g	<10	10	<1	1	<0.1	0.1	9883474
Aroclor 1016	ug/g	<10	10	<1	1	<0.1	0.1	9883474
Aroclor 1221	ug/g	<10	10	<1	1	<0.1	0.1	9883474
Aroclor 1232	ug/g	<10	10	<1	1	<0.1	0.1	9883474
Aroclor 1242	ug/g	<10	10	<1	1	0.2	0.1	9883474
Aroclor 1248	ug/g	<10	10	22	1	<0.1	0.1	9883474
Aroclor 1254	ug/g	157	10	<1	1	<0.1	0.1	9883474
Aroclor 1260	ug/g	<10	10	2	1	<0.1	0.1	9883474
Aroclor 1268	ug/g	<10	10	<1	1	<0.1	0.1	9883474
Total PCB	ug/g	157	10	24	1	0.2	0.1	9883474
Surrogate Recovery (%)								
Decachlorobiphenyl	%	NC		123		87		9883474
RDL = Reportable Detection Limit								
QC Batch = Quality Control Batch								



BUREAU
VERITAS

Bureau Veritas Job #: C521264

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: KILBRIDE

Sampler Initials: BW

POLYCHLORINATED BIPHENYLS BY GC-ECD (SOLID)

Bureau Veritas ID		AOLK12		
Sampling Date		2025/02/18		
COC Number		N/A		
	UNITS	P0004, COMPOSITE, 1959, LOC:143, CORRIDOR	RDL	QC Batch
PCBs				
Aroclor 1262	ug/g	<0.1	0.1	9883474
Aroclor 1016	ug/g	<0.1	0.1	9883474
Aroclor 1221	ug/g	<0.1	0.1	9883474
Aroclor 1232	ug/g	<0.1	0.1	9883474
Aroclor 1242	ug/g	<0.1	0.1	9883474
Aroclor 1248	ug/g	0.7	0.1	9883474
Aroclor 1254	ug/g	<0.1	0.1	9883474
Aroclor 1260	ug/g	<0.1	0.1	9883474
Aroclor 1268	ug/g	<0.1	0.1	9883474
Total PCB	ug/g	0.7	0.1	9883474
Surrogate Recovery (%)				
Decachlorobiphenyl	%	97		9883474
RDL = Reportable Detection Limit				
QC Batch = Quality Control Batch				



BUREAU
VERITAS

Bureau Veritas Job #: C521264

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: KILBRIDE

Sampler Initials: BW

GENERAL COMMENTS

Results relate only to the items tested.



BUREAU
VERITAS

Bureau Veritas Job #: C521264

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: KILBRIDE

Sampler Initials: BW

QUALITY ASSURANCE REPORT

QA/QC Batch	Init	QC Type	Parameter	Date Analyzed	Value	Recovery	UNITS	QC Limits
9883474	FMA	Matrix Spike	Decachlorobiphenyl	2025/03/03	90	%	30 - 130	
			Aroclor 1260	2025/03/03	110	%	30 - 130	
			Total PCB	2025/03/03	110	%	30 - 130	
9883474	FMA	Spiked Blank	Decachlorobiphenyl	2025/03/03	106	%	30 - 130	
			Aroclor 1260	2025/03/03	129	%	30 - 130	
			Total PCB	2025/03/03	129	%	30 - 130	
9883474	FMA	RPD	Aroclor 1260	2025/03/03	6.7	%	50	
			Total PCB	2025/03/03	200 (1)	%	50	
9883474	FMA	Method Blank	Aroclor 1262	2025/03/03	<0.1		ug/g	
			Decachlorobiphenyl	2025/03/03		110	%	30 - 130
			Aroclor 1016	2025/03/03	<0.1		ug/g	
			Aroclor 1221	2025/03/03	<0.1		ug/g	
			Aroclor 1232	2025/03/03	<0.1		ug/g	
			Aroclor 1242	2025/03/03	<0.1		ug/g	
			Aroclor 1248	2025/03/03	<0.1		ug/g	
			Aroclor 1254	2025/03/03	<0.1		ug/g	
			Aroclor 1260	2025/03/03	<0.1		ug/g	
			Aroclor 1268	2025/03/03	<0.1		ug/g	
			Total PCB	2025/03/03	<0.1		ug/g	

Duplicate: Paired analysis of a separate portion of the same sample. Used to evaluate the variance in the measurement.

Matrix Spike: A sample to which a known amount of the analyte of interest has been added. Used to evaluate sample matrix interference.

Spiked Blank: A blank matrix sample to which a known amount of the analyte, usually from a second source, has been added. Used to evaluate method accuracy.

Method Blank: A blank matrix containing all reagents used in the analytical procedure. Used to identify laboratory contamination.

Surrogate: A pure or isotopically labeled compound whose behavior mirrors the analytes of interest. Used to evaluate extraction efficiency.

(1) Recovery or RPD for this parameter is outside control limits. The overall quality control for this analysis meets acceptability criteria.



BUREAU
VERITAS

Bureau Veritas Job #: C521264

Report Date: 2025/03/04

Pinchin Ltd

Client Project #: 352316.001

Site Location: KILBRIDE

Sampler Initials: BW

VALIDATION SIGNATURE PAGE

The analytical data and all QC contained in this report were reviewed and validated by:

Louise Harding, Scientific Specialist

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.



6740 Campobello Road, Mississauga, Ontario L5N 2L8

Phone: 905-817-5700 Fax: 905-817-5779 Toll Free: 800-563-6266
CAM FCD-01191/6

CHAIN OF CUSTODY RECORD

Page _____ of _____

Invoice Information		Report Information (if differs from invoice)		Project Information (where applicable)		Turnaround Time (TAT) Required			
Company Name: Pinchin Ltd.		Company Name:		Quotation #:		<input checked="" type="checkbox"/> Regular TAT (5-7 days) Most analyses			
Contact Name: Ben Weir / Emily Balfour / Jessica Cozzitorto		Contact Name:		P.O. #/ AFE#:		PLEASE PROVIDE ADVANCE NOTICE FOR RUSH PROJECTS			
Address:		Address:		Project #:	352316.001	Rush TAT (Surcharges will be applied)			
Phone:	Fax:	Phone:	Fax:	Site Location:	Kilbride	<input type="checkbox"/> 1 Day	<input type="checkbox"/> 2 Days	<input type="checkbox"/> 3-4 Days	
Email: bweir@pinchin.com / ebalfour@pinchin.com /		Email:		Site #:		Date Required: 03-Mar-25			
MOE REGULATED DRINKING WATER OR WATER INTENDED FOR HUMAN CONSUMPTION MUST BE SUBMITTED ON THE BUREAU VERITAS DRINKING WATER CHAIN OF CUSTODY						Rush Confirmation #: _____			
Regulation 153		Other Regulations		Analysis Requested		LABORATORY USE ONLY			
<input type="checkbox"/> Table 1 <input type="checkbox"/> Res/Park <input type="checkbox"/> Med/ Fine <input type="checkbox"/> Table 2 <input type="checkbox"/> Ind/Comm <input type="checkbox"/> Coarse <input type="checkbox"/> Table 3 <input type="checkbox"/> Agri/ Other <input type="checkbox"/> Table _____		<input type="checkbox"/> CCME <input type="checkbox"/> Sanitary Sewer Bylaw <input type="checkbox"/> MISA <input type="checkbox"/> Storm Sewer Bylaw <input type="checkbox"/> PWQO Region _____ <input type="checkbox"/> Other (Specify) _____		# OF CONTAINERS SUBMITTED FIELD FILTERED (CIRCLE) Metals / Hg / CrVI BTEX/ PHC F1 PHCs F2 - F4 VOCs REG 153 METALS & INORGANICS REG 153 ICPMS METALS REG 153 METALS (Hg, Cr VI, ICPMS Metals, HgS - B) Lead (Pb) in Paints PCBs		CUSTODY SEAL Y / N Present <input type="checkbox"/> Intact <input checked="" type="checkbox"/> COOLER TEMPERATURES			
FOR RSC (PLEASE CIRCLE) <input type="checkbox"/> Y / N REG 558 (MIN. 3 DAY TAT REQUIRED) REG 406 Table _____									
Include Criteria on Certificate of Analysis: <input type="checkbox"/> Y / <input checked="" type="checkbox"/> N						HOLD - DO NOT ANALYZE COOLING MEDIA PRESENT: <input type="checkbox"/> Y / <input checked="" type="checkbox"/> N COMMENTS			
SAMPLE IDENTIFICATION				DATE SAMPLED (YYYY/MM/DD)	TIME SAMPLED (HH:MM)	MATRIX			
P0001, Composite, 1967,Loc:111,Classroom				2025/02/18	PM	BULK			
P0002, Composite, 1967,Loc:150,Exterior				2025/02/18	PM	BULK			
P0003, Composite, 1959,Loc:150,Exterior				2025/02/18	PM	BULK			
P0004, Composite, 1959,Loc:143,Corridor				2025/02/18	PM	BULK			
RELINQUISHED BY: (Signature/Print)		DATE: (YYYY/MM/DD)	TIME: (HH:MM)	RECEIVED BY: (Signature/Print)		DATE: (YYYY/MM/DD)	TIME: (HH:MM)	BV JOB #	
Emily Balfour		2025/02/24	2:00PM	Suzan Sturton		2025/02/27	10:55		

Unless otherwise agreed to in writing, work submitted on this Chain of Custody is subject to Bureau Veritas' standard Terms and Conditions. Signing of this Chain of acceptance of our terms available at <https://www.bvna.com/coc-terms-and-conditions>



NONT-2025-02-4600

APPENDIX III
Methodology

1.0 GENERAL

An investigation was conducted to identify the type of Hazardous Building Materials incorporated in the structure and its finishes.

Information regarding the location and condition of hazardous building materials encountered and visually estimated quantities were recorded. The locations of any samples collected were recorded on small-scale plans. As-built drawings and previous reports were referenced where provided.

Sample collection was conducted in accordance with our Standard Operating Procedures.

1.1 Asbestos

The investigation for asbestos included friable and non-friable asbestos-containing materials (ACM). A friable material is a material that when dry can be crumbled, pulverized or powdered by hand pressure, or a material that has already become crushed, pulverized, or powdered.

A separate set of samples was collected of each type of homogenous material suspected to contain asbestos. A homogenous material is defined by the US EPA as material that is uniform in texture and appearance, was installed at one time, and is unlikely to consist of more than one type or formulation of material. The homogeneous materials were determined by visual examination and available information on the phases of construction and prior renovations.

Samples were collected at a rate that is in compliance with the requirements of local regulations and guidelines. The sampling strategy was also based on known ban dates and phase out dates of the use of asbestos; sampling of certain building materials is not conducted after specific construction dates. In addition, to be conservative, several years past these dates are added to account for some uncertainty in the exact start / finish date of construction and associated usage of ACM. In some cases, manufactured products such as asbestos cement pipe were visually identified without sample confirmation.

The asbestos analysis of select materials was completed using a stop-positive approach. Only one result meeting the regulated criteria was required to determine that a material is asbestos-containing, but all samples must be analyzed to conclusively determine that a material is non-asbestos. The laboratory stopped analyzing samples from a homogeneous material once a result equal to or greater than the regulated criteria is detected in any of the samples of that material. All samples of a homogeneous material were analyzed if no asbestos is detected. In some cases, all samples were analyzed in the sample set regardless of result.

The analysis was performed in accordance with Test Method EPA/600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials, July 1993.

Analytical results were compared to the following criteria:

Jurisdiction	Friable	Non-Friable
Ontario	0.5%	0.5%

Where building materials are described in the report as “non-asbestos” or “does not contain asbestos”, this means that either no asbestos was detected by the analytical method utilized in any of the multiple samples or, if detected, it is below the lower limit of an asbestos-containing material in the applicable regulation. Additionally, these terms are used for materials which historically are known to not include asbestos in their manufacturing.

Asbestos materials were evaluated in order to make recommendations regarding any remedial work. The priority for remedial action was based on several factors:

- Friability (friable or non-friable)
- Condition (good, fair, poor, debris)
- Accessibility (ranking from accessible to all building users to inaccessible)
- Visibility (whether the material is obscured by other building components)
- Efficiency of the work (for example, if damaged ACM is being removed in an area, it may be most practical to remove all ACM in the area even if it is in good condition)

1.2 Lead

Samples of distinctive paint finishes, and surface coatings present in more than a limited application, where removal of the paint is possible were collected. The samples were collected by scraping the painted finish to include base and covering applications.

Analysis for lead in paints or surface coatings was performed in accordance with EPA Method No. 3050B/EPA SW-846-6020B0B, inductively coupled plasma – mass spectrometry.

Analytical results were compared to the following criteria.

Jurisdiction	Units (%)	Units (ppm) / (mg/kg)
Ontario	0.009	90

Other lead building products (e.g. batteries, lead sheeting, flashing) were identified by visual observation only.

1.3 Silica

Building materials known to contain crystalline silica (e.g. concrete, cement, tile, brick, masonry, mortar) were identified by visual inspection only. Pinchin did not perform sampling of these materials for laboratory analysis of crystalline silica content.

1.4 Mercury

Building materials, products or equipment (e.g. thermostats, barometers, pressure gauges, lamp tubes), suspected to contain mercury were identified by visual inspection only. Dismantling of equipment suspected of containing mercury was not performed. Sampling of these materials for laboratory analysis of mercury content was not performed.

1.5 Polychlorinated Biphenyls

The potential for light ballast and oil filled transformers to contain PCBs was based on the age of the building, a review of maintenance records, and examination of labels or nameplates on equipment, where present and accessible. The information was compared to known ban dates of PCBs and Environment Canada publications.

Dry type transformers were presumed to be free of dielectric fluids and hence non-PCB.

Fluids (mineral oil, hydraulic, Aroclor or Askarel) in transformers or other equipment were not sampled for PCB content.

Caulking, sealants, or paints were sampled and submitted for PCB analysis following EPA 3550C/8082A.

Sample results are compared to the criteria of 50 mg/kg for solids as stated in the PCB Regulation, SOR/2008-273.

1.6 Visible Mould

The presence of mould or water damage was determined by visual inspection of exposed building surfaces. If any mould growth or water damage was concealed within building cavities it was not addressed in this assessment.

Template: Methodology for Hazardous Building Materials Assessment, HAZ, November 13 2024

APPENDIX IV
Location Summary Report

Client: Halton District School Board
Building Name: Kilbride Public School
Survey Date: 2024-08-07
Building Phases: A: 1959

Site: 6611 Panton Street, Burlington, ON

Last Re-Assessment:

Location No.	Name or Description	Area ft ²	Floor No.	Bldg. Phase	Notes
100	Main Office, room no. 101	160	1	A	
101	Principals Office, room no. 101	150	1	A	
102	Classroom, room no. 102	815	1	A	
103	Classroom, room no. 103	815	1	A	
104	Classroom / Storage, room no. 104/105A	490	1	A	
105	Classroom / Storage, room no. 105	880	1	C	
106	Classroom, room no. 106	880	1	C	
107	Classroom, room no. 107	815	1	A	
108	Classroom, room no. 108	815	1	A	
109	Classroom, room no. 109	815	1	A	
110	Classroom, room no. 110	700	1	B	
111	Classroom, room no. 111	700	1	B	
112	Classroom, room no. 112	700	1	B	
113	Classroom, room no. 113-A	1150	1	B	
114	Classroom, room no. 114	700	1	B	
115	Classroom, room no. 115	330	1	A	
116	Library, room no. 116-A-B-C-D	0	1	A	No access above ceiling- Height restrictions (15ft)
117	Washroom, room no. 117	30	1	A	
118	Washroom, room no. 118	30	1	A	
119	Washroom, room no. 119	30	1	A	
120	Mechanical Room, room no. 120-A	300	1	A	
121	Office, room no. 121	110	1	A	
122	Boy's Washroom, room no. 122	220	1	A	
123	Girl's Washroom, room no. 123	220	1	A	
124	Supply Room, room no. 124	570	1	B	
125	Classroom, room no. 125-A	450	1	B	
126	Office / Washroom, room no. 126-A	125	1	B	
127	Storage / Corridor, room no. 127-A-B	550	1	B	
128	Kitchen, room no. 128	720	1	C	
129	Equipment Storage, room no. 129	320	1	C	
130	Equipment Storage, room no. 130	320	1	C	
131	Equipment Storage, room no. 131	320	1	C	
132	Gymnasium, room no. 132	4000	1	C	
133	Storage, room no. 133-A	115	1	C	
134	Changeroom, room no. 134	400	1	C	
135	Washroom, room no. 135	400	1	C	
136	Changeroom, room no. 136-A	400	1	C	
137	Washroom, room no. 137-A	400	1	C	
138	Gym Office, room no. 138-A	115	1	C	
139	Corridor, room no. 139	250	1	C	
140	Corridor, room no. 140-A-B-C	850	1	C	
141	Corridor, room no. 141-A	370	1	B	
142	Cubby Area, room no. 142	180	1	B	
143	Corridor, room no. 143	750	1	A	
144	Corridor, room no. 144	1080	1	A	
145	Corridor, room no. 145-A	340	1	C	
146	Stairwell, room no. 146	100	1/2	C	
147	Mezzanine Mechanical Room, room no. 147	1000	1	C	
148	JK / SK Classroom, room no. 116	1200	1	D	
149	JK / SK Classroom, room no. 117	700	1	D	
150	Exterior 1967 Era	0		B	
151	Exterior 1959 Era	0		A	
152	Exterior 1984 Era	0		C	

Location No.	Name or Description	Area ft ²	Floor No.	Bldg. Phase	Notes
153	Exterior 2009 Era	0		D	
158	Roofs	0		A	Era 1959, 1967, 1984, 2009
1959	1959 Samples	0		A	
1967	1967 Samples	0		A	
1984	1984 Samples	0		A	
2009	2009 Samples	0		A	

APPENDIX V
Hazardous Materials Summary Report / Sample Log

Client: Halton District School Board

Site: 6611 Panton Street, Burlington, ON

Building Name: Kilbride Public School

Survey Date: 2024-08-07

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	S0001	Floor Vinyl Floor Tile 9x9 Beige With White And Brown Streaks	108,109,1959	A	0	1630	0	100	Chrysotile	Yes	NF
Asbestos	S0002	Floor Mastic, Black 9x9 Beige With White And Brown Streaks	108,109,1959	A	0	0	0	100	None Detected	No	
Asbestos	S0003	Floor Mastic, Black 9x9 Green	102,103,1959	A	0	0	0	100	None Detected	No	
Asbestos	S0004	Floor Vinyl Floor Tile 12x12 Dark Beige With Dark Beige Fleck	105,106,1967	A,C	0	0	0	100	None Detected	No	
Asbestos	S0005	Floor Vinyl Floor Tile 12x12 Cream	1967	A	0	0	0	100	None Detected	No	
Asbestos	S0006	Floor Mastic, Black 12x12 Cream	1967	A	0	0	0	100	None Detected	No	
Asbestos	S0007	Floor Mastic, Black 12x12 Dark Beige With Dark Beige Fleck	126,1967	A,B	0	0	0	100	None Detected	No	
Asbestos	S0008	Floor Mastic, Black 12x12 Light Green	104,1959	A	0	0	0	100	None Detected	No	
Asbestos	S0009	Floor Mastic, Black 12x12 Cream With Maroon	105,106,1959	A,C	0	0	0	100	None Detected	No	
Asbestos	S0010	Floor Mastic, Black 12x12 Light Beige	100,101,110,112,113,114,115,116,117,127,1959	A,B	0	0	0	100	None Detected	No	
Asbestos	S0011	Floor Mastic, Black 12x12 White	124,1967	A,B	0	570	0	100	Chrysotile	Yes	NF
Asbestos	S0012	Wall Mastic, Brown Black Baseboards	110,111,112,113,114,124,125,126,127,143,1967	A,B	0	0	0	100	None Detected	No	
Asbestos	S0013	Wall Mastic, Brown Brown Baseboards	105,106,1984	A,C	0	0	0	100	None Detected	No	
Asbestos	S0014	Other Window Caulking Grey	102,103,104,107,108,109,1959	A	0	0	0	100	None Detected	No	
Asbestos	S0015	Other Window Caulking Black	105,106,150,152,1984	A,B,C	80	0	0	100	Chrysotile	Yes	NF
Asbestos	S0016 DEFG	Wall Paint Concrete Block	100,101,102,103,104,107,108,109,115,116,117 118,119,120,121,122,123,143,144,1959	A	0	0	0	100	None Detected	No	
Asbestos	S0017 DEFG	Wall, Structure, Wall Paint Concrete Block	110,111,112,113,114,124,125,126,127,141,142 143,1967	A,B	0	0	0	100	None Detected	No	
Asbestos	S0018 DEFG	Wall Paint Concrete Block	105,106,128,132,133,134,135,136,137,138,139 140,145,1984	A,C	0	0	0	100	None Detected	No	
Asbestos	S0019	Wall Mortar Concrete Block	100,101,102,103,104,107,108,109,115,116,117 118,119,120,121,122,123,143,144,1959	A	0	0	0	100	None Detected	No	
Asbestos	S0020	Wall, Structure, Wall Mortar Concrete Block	110,111,112,113,114,124,125,126,127,141,142 143,1967	A,B	0	0	0	100	None Detected	No	
Asbestos	S0021	Wall Mortar Concrete Block	105,106,128,129,130,131,132,133,134,135,136 137,138,139,140,145,146,147,1984	A,C	0	0	0	100	None Detected	No	
Asbestos	S0022	Wall Vermiculite	110,111,112,113,114,124,125,126,127,140,141 142,143,1967	A,B,C	0	0	0	100	Actinolite	Yes	F
Asbestos	S0023	Piping Sweatwrap	115,116,120,121,143,144,1959	A	322	0	0	100	Chrysotile	Yes	F
Asbestos	S0024	Structure Caulking Siporex	100,101,102,103,104,105,106,107,108,109,115 116,117,118,119,120,121,122,123,143,144,145 1959	A,C	0	0	0	100	None Detected	No	
Asbestos	S0025	Wall, Other, Wall Fascia Cement Product	115,151,1959	A	0	80	0	100	Chrysotile	Yes	NF

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
		Transite									
Asbestos	S0026	Piping Parging Cement	126,127,141,142,143,1967	A,B	0	0	25	100	Chrysotile	Yes	F
Asbestos	S0027	Other Window Caulking White	150,1967	A,B	0	0	0	100	Chrysotile	Yes	NF
Asbestos	S0028	Wall Rubber Brown Baseboards	105,106,1984	A,C	0	0	0	100	None Detected	No	
Asbestos	S0029	Floor Vinyl Floor Tile 12x12 Light Beige With Beige Flecks	100,101,110,111,112,113,114,115,116,117,127 1959	A,B	0	0	0	100	None Detected	No	
Asbestos	S0030	Floor Vinyl Floor Tile 12x12 Dark Beige With Dark Beige Flecks	126,128,129,130,133,138,1959,1967,2009	A,B,C	0	0	0	100	None Detected	No	
Asbestos	S0031	Floor Vinyl Floor Tile 9x9 Green	102,103,1959	A	0	1630	0	100	Chrysotile	Yes	NF
Asbestos	S0032	Floor Vinyl Floor Tile 12x12 Light Green	104,1959	A	0	0	0	100	None Detected	No	
Asbestos	S0033	Floor Vinyl Floor Tile 12x12 White/beige With Beige Flecks	107,116,121,1959	A	0	0	0	100	None Detected	No	
Asbestos	S0034	Floor Vinyl Floor Tile 12x12 Cream/wheat With Purple Fleck	110,125,1967	A,B	0	0	0	100	None Detected	No	
Asbestos	S0035	Floor Vinyl Floor Tile 12x12 White/green With Directional Fleck	124,1967	A,B	0	570	0	100	Chrysotile	Yes	NF
Asbestos	S0036	Wall Plaster Textured	110,111,112,127,1967	A,B	0	0	0	100	None Detected	No	
Asbestos	S0037	Ceiling Soffit Plaster Textured	141,150,1967	A,B	0	240	0	100	Chrysotile	Yes	PF
Asbestos	S0038	Wall Drywall And Joint Compound	103,104,108,109,116,121,1959	A	0	0	0	100	None Detected	No	
Asbestos	S0039	Wall, Ceiling, Wall Drywall And Joint Compound	105,106,134,135,136,137,139,140,145,1984	A,C	0	0	0	100	None Detected	No	
Asbestos	S0040	Wall Bulkhead Drywall And Joint Compound	110,111,112,113,114,124,125,127,1967	A,B	0	0	0	100	None Detected	No	
Asbestos	S0041	Wall Rubber Black Baseboards	110,111,112,113,114,124,125,126,127,143,1967	A,B	0	0	0	100	None Detected	No	
Asbestos	S0042	Ceiling Acoustic Tile Ceiling Tiles (lay-in) 24x48 Pinhole With Dense Fissures	116,128,133,138,141,142,1959	A,B,C	0	0	0	100	None Detected	No	
Asbestos	S0043	Ceiling Acoustic Tile Ceiling Tiles (lay-in) 24x48 Pinhole With Width Wide Fissures	113,116,125,126,127,128,133,138,139,140,141 142,1959	A,B,C	0	0	0	100	None Detected	No	
Asbestos	S0044	Ceiling Acoustic Tile Ceiling Tiles (lay-in) 24x48 Pinhole With Fleck	104,116,121,122,123,139,140,141,142,1959	A,B,C	0	0	0	100	None Detected	No	
Asbestos	S0045	Ceiling Acoustic Tile Ceiling Tiles (lay-in) 24x48 Random Fissures	116,1959	A	0	0	0	100	None Detected	No	
Asbestos	S0046	Piping Parging Cement	127,141,142,143,1967	A,B	0	0	12	100	Chrysotile	Yes	F
Asbestos	S0047	Piping Parging Cement	116,120,143,1959	A	0	0	35	100	Chrysotile	Yes	F
Asbestos	S0048	Piping Parging Cement	115,116,119,120,121,143,1959	A	0	0	51	100	Chrysotile	Yes	F
Asbestos	S0049 ABC	Other Sink Mastic, Gold	105,109,128	A,C	0	0	13	0	Chrysotile	Yes	NF
Asbestos	S0050 A	Wall Vermiculite	107	A	0	0	0	100	Suspect Material	Yes	F
Asbestos	S0051	Other Window Caulking	150,1967	A,B	0	0	0	100	Chrysotile	Yes	NF
Asbestos	V0052	Wall Mortar Exterior Brick	105,107,115,123,143,1959	A,C	0	0	0	100	None Detected	No	
Asbestos	S0053	Wall Mortar Exterior Brick	110,111,112,113,114,125,126,140,141,143,1967	A,B,C	0	0	0	100	None Detected	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	S0054	Wall Mortar Exterior Brick	132,133,134,140,1984	A,C	0	0	0	100	None Detected	No	
Asbestos	S0055 ABC	Other Door Putty Window, Door 1	143	A	55	0	0	0	Chrysotile	Yes	NF
Asbestos	S0056 ABC	Floor Mastic, Black	107,121	A	0	925	0	0	None Detected	No	
Asbestos	S0057 ABC	Other Door Caulking Door 1	143	A	0	0	0	0	None Detected	No	
Asbestos	S0058 ABC	Other Door Caulking	151	A	217	0	0	0	Chrysotile	Yes	NF
Asbestos	S0059 ABC	Floor Mastic, Black And Levelling	111	B	0	0	0	100	None Detected	No	
Asbestos	S0060 ABC	Floor Vinyl Floor Tile And Mastic And Levelling	126	B	0	125	0	0	Chrysotile	Yes	NF
Asbestos	S0061 ABC	Floor Vinyl Floor Tile And Mastic 12x12 White	112,114,125	B	0	0	0	0	Chrysotile	Yes	NF
Asbestos	S0062 ABC	Floor Mastic	128	C	0	0	0	0	None Detected	No	
Asbestos	S0063 ABC	Wall Door, Expansion Joint Caulking	111,126,141	B	0	0	0	0	None Detected	No	
Asbestos	S0064 ABC	Other Window Putty	126,141	B	75	0	0	0	Chrysotile	Yes	NF
Asbestos	S0065 ABC	Piping Tar	126	B	0	0	0	0	None Detected	No	
Asbestos	S0066 ABC	Other Window Putty	140,145	C	100	0	0	0	Chrysotile	Yes	NF
Asbestos	S0067 ABC	Other Door Caulking	152	C	100	0	0	0	Chrysotile	Yes	NF
Asbestos	S0068 ABC	Other, Wall Door Caulking Door 11	116,132,140,145	A,C	192	0	0	0	Chrysotile	Yes	NF
Asbestos	S0069 ABC	Floor Floor Levelling Compound	132	C	0	0	0	0	None Detected	No	
Asbestos	S0070 ABC	Floor Terrazzo	140,141,145	B,C	0	0	0	0	None Detected	No	
Asbestos	S0071 ABC	Wall Plaster Parging On Foundation, Outside Library	151	A	0	0	0	0	None Detected	No	
Asbestos	S0072 ABC	Piping Gasket Red	120	A	0	0	0	0	None Detected	No	
Asbestos	S0073 ABC	Other Tar	120	A	0	0	0	100	None Detected	No	
Asbestos	S0074 ABC	Other Door Caulking Grey	150	B	60	0	0	0	Chrysotile	Yes	NF
Asbestos	S0075 ABC	Other Tar Tar On Canopy Roof	151	A	0	130	0	0	None Detected	No	
Asbestos	S0076 ABC	Other Tar Tar On Roof Penetration Above Mechanical Room	151	A	0	10	0	0	None Detected	No	
Asbestos	S0077 ABC	Floor Vinyl Floor Tile And Mastic 12x12 Grey With Beige Fleck	127	B	0	40	0	0	None Detected	No	
Asbestos	S0078 AB	Wall Vermiculite	103,104	A	0	0	0	0	Asbestos Containing	Yes	F
Asbestos	V9000	Wall Cement Product Door #1, Transite Board Above Exterior Door 1	143,151	A	0	290	0	0	Confirmed Asbestos	Yes	NF
Asbestos	V9500	Floor Mastic	107	A	0	815	0	0	Presumed Asbestos	Yes	NF
Asbestos	V9500	Floor Vinyl Floor Tile 9x9	107,115	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Floor Vinyl Floor Tile And Mastic 9x9 Red And Beige	116	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other Precast Refractory Brick Kiln	106	C	0	0	1	0	Presumed Asbestos	Yes	NF

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	V9500	Other Roofing Material	158	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Wall Vermiculite 1959	100,101,102,103,104,105,107,108,109,115,116 117,118,119,120,121,122,123,143,150,151	A,B,C	0	0	0	100	Presumed Asbestos	Yes	F
Asbestos	V0000	Ceiling Acoustic Tile Ceiling Tiles (lay-in) 24x48 Pinhole With Fleck	117,148,149	A,D	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Acoustic Tile Ceiling Tiles (lay-in) 24x48 Textured	127	B	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Drywall And Joint Compound	145	C	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Duct Mastic, Red Silicone	120	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Foam Sheeting, Faux Wood	132	C	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile 12x12 Dark Beige With Dark Beige Flecks	149	D	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile 12x12 Blue With Blue Flecks	149	D	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Sheet Flooring Beige And Blue With Speckles	148	D	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall Drywall And Joint Compound	148,149	D	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall Mortar	149	D	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall Mortar Concrete Block	148	D	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall Paint	149	D	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall Paint Concrete Block	148	D	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall Spandrel Panel Styrofoam Library Panels	150	B	0	0	0	0	Non Asbestos	No	
Paint	L0001	Floor Concrete (poured) Grey	120	A	0	300	0	0	Lead (High)	Yes	-
Paint	L0002	Wall Concrete (precast) Light Green	120	A	0	600	0	0	Lead (High)	Yes	-
Paint	L0003	Piping Metal Blue	120	A	0	8	0	0	Lead (High)	Yes	-
Paint	L0004	Piping Metal Yellow	120	A	0	45	0	0	Lead (Low)	Yes	-
Paint	L0005	Wall Concrete (precast) Light Beige	102,103,104,105,106,107,108,109,115,121	A,C	0	17600	0	0		No	-
Paint	L0006	Wall Concrete (precast) Light Pink	114	B	0	1400	0	0	Lead (High)	Yes	-
Paint	L0007	Wall Concrete (precast) Cream	125,126,143	A,B	0	750	0	0	Lead (High)	Yes	-
Paint	L0008	Wall Concrete (precast) Light Cream	110,111,112,127	B	0	4800	0	0	Lead (High)	Yes	-
Paint	L0009	Ceiling Drywall And Joint Compound Beige	145	C	0	0	0	0		No	-
Paint	L0010	Other Metal Blue, Doors	150,151,152	A,B,C	0	0	0	100		No	-
Paint	L0011	Other Wood White On Canopy Beam	151	A	0	0	0	100	Lead (High)	Yes	-
Paint	L0012	Other Wood Brown On Canopy Deck	151	A	0	0	0	100	Lead (High)	Yes	-
Paint	L0013	Ceiling Drywall And Joint Compound White On Soffit, Door 11	152	C	0	0	0	0		No	-
Paint	L0014	Wall Concrete Block Cream/blue	140	C	0	0	0	0		No	-
Paint	L0015	Mechanical Equipment Metal White On Metal Cushion Tank	120	A	0	40	0	0	Lead (Low)	Yes	-

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Paint	L0016	Wall Concrete (precast) Cream On Block	143	A	0	1500	0	0		No	-
Lead Product	V9000	Batteries (other)	120	A	0	0	1	0	Lead Product	Yes	-
Lead Product	V9500	Batteries In Emer. Lights	104,121	A	0	0	2	0	Presumed Lead Product	Yes	-
PCB	P0001	Caulking Composite, 1967	111,112,126,141,143	A,B	0	0	0	100	-	Yes	-
PCB	P0002	Caulking Composite, 1967	150	B	0	0	0	100	-	No	-
PCB	P0003	Caulking Composite, 1959	150	B	0	0	0	100	-	No	-
PCB	P0004	Caulking Composite, 1959	116,143	A	0	0	0	100	-	No	-
PCB	V0000	Transformer	120	A	0	0	1	0	-	No	-
Hg	V9000	Thermostat	120	A	0	0	1	0	Hg	Yes	-
Hg	V0000	Light Fixture	102,103,104,105,106,107,108,109,110,111,112 114,115,116,121,125,127,128,140,141,143,144 145	A,B,C	0	0	344	0	-	No	-

Legend:

Sample number	Units	
S####	Asbestos sample collected	SF Square feet
L####	Paint sample collected	LF Linear feet
P####	PCB sample collected	EA Each
M####	Mould sample collected	% Percentage
V####	Material visually similar to numbered sample collected	
V0000	Known non Hazardous Material	NF Non Friable material.
V9000	Material is visually identified as Hazardous Material	F Friable material
V9500	Material is presumed to be Hazardous Material	PF Potentially Friable material
[Loc. No.]	Abated Material	

APPENDIX VI
HMIS All Data Report

Client: Halton District School Board
Location: #100 : Main Office
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 101
Last Re-Assessment: 0000-00-00

Area (sqft): 160

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		None Found														
Floor		Carpet			A	Y										
Floor		Mastic, Black, 12x12 Light beige with beige flecks		Vinyl Floor Tile	D	N		100			%	V0010	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Light beige with beige flecks			A	Y		100			%	V0029	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		None Found														
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

Client: Halton District School Board
Location: #101 : Principals Office
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 101
Last Re-Assessment: 0000-00-00

Area (sqft): 150

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		None Found														
Floor		Carpet			A	Y										
Floor		Mastic, Black, 12x12 Light beige with beige flecks		Vinyl Floor Tile	D	N		100			%	V0010	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Light beige with beige flecks			D	N		100			%	V0029	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		Fibreglass			A	Y										
Piping		Fibreglass			C	Y										
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

Client: Halton District School Board
Location: #102 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 102
Last Re-Assessment: 0000-00-00

Area (sqft): 815

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Mastic, Black, 9x9 Green		Vinyl Floor Tile	D	N		100			%	V0003	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 9x9 Green			A	Y		815(7)			SF	V0031	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Mechanical Equipment		None Found														
Other	Window	Caulking, Grey			A	Y		100			%	V0014	None Detected	N.D.	None	
Piping		Fibreglass			C	Y										
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

Client: Halton District School Board
Location: #102 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 102
Last Re-Assessment: 0000-00-00

Area (sqft): 815

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	1760		SF	V0005	Light beige			Pb: 0.0043 %	No

Client: Halton District School Board
Location: #102 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 102
Last Re-Assessment: 0000-00-00

Area (sqft): 815

MERCURY					
Component	Quantity	Unit	Sample	Hazard	
Light Fixture ¹	16	EA	V0000		

1 - LEDs

Client: Halton District School Board
Location: #103 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 103
Last Re-Assessment: 0000-00-00

Area (sqft): 815

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Mastic, Black, 9x9 Green		Vinyl Floor Tile	D	N		100			%	V0003	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 9x9 Green			A	Y		815(7)			SF	V0031	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Mechanical Equipment		None Found														
Other	Window	Caulking, Grey			A	Y		100			%	V0014	None Detected	N.D.	None	
Piping		Fibreglass			C	Y										
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0038	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F
Wall		Vermiculite			D	N						S0078A	Asbestos Containing		Confirmed Asbestos	F

Client: Halton District School Board
Location: #103 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 103
Last Re-Assessment: 0000-00-00

Area (sqft): 815

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	1760		SF	V0005	Light beige			Pb: 0.0043 %	No

Client: Halton District School Board
Location: #103 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 103
Last Re-Assessment: 0000-00-00

Area (sqft): 815

MERCURY										
Component	Quantity	Unit	Sample	Hazard						
Light Fixture ¹	16	EA	V0000							

1 - LEDs

Client: Halton District School Board
Location: #104 : Classroom / Storage
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 104/105A
Last Re-Assessment: 0000-00-00

Area (sqft): 490

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y		100			%	V0044	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Mastic, Black, 12x12 Light green		Vinyl Floor Tile	D	N		100			%	V0008	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Light green			A	Y		100			%	V0032	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Window	Caulking, Grey			A	Y		100			%	V0014	None Detected	N.D.	None	
Piping		Fibreglass			A	Y										
Structure		Concrete (precast)			C	N										
Structure		Caulking, Siporex			C	N		100			%	V0024	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0038	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	S0016D	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F
Wall		Vermiculite			D	N						S0078B	Asbestos Containing		Confirmed Asbestos	F

Client: Halton District School Board
Location: #104 : Classroom / Storage
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 104/105A
Last Re-Assessment: 0000-00-00

Area (sqft): 490

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	1760		SF	V0005	Light beige			Pb: 0.0043 %	No

Client: Halton District School Board
Location: #104 : Classroom / Storage
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 104/105A
Last Re-Assessment: 0000-00-00

Area (sqft): 490

PB PRODUCTS					
Component	Quantity	Unit	Sample	Hazard	
Batteries In Emer. Lights	1	EA	V9500	Presumed	

Client: Halton District School Board
Location: #104 : Classroom / Storage
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 104/105A
Last Re-Assessment: 0000-00-00

Area (sqft): 490

MERCURY					
Component	Quantity	Unit	Sample	Hazard	
Light Fixture ¹	16	EA	V0000		



ALL DATA REPORT



1 - LEDs

Client: Halton District School Board
Location: #105 : Classroom / Storage
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 105
Last Re-Assessment: 0000-00-00

Area (sqft): 880

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Duct		Not Insulated			C	Y										
Floor		Mastic, Black, 12x12 Cream with maroon		Vinyl Floor Tile	D	N		100			%	V0009	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige fleck			A	Y		100			%	V0004	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Sink	Mastic, Gold			A	Y		9(7)			EA	S0049A	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other	Window	Caulking, Black			A	Y		40(7)			LF	V0015	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Piping		Fibreglass			A	Y										
Piping		Fibreglass			C	Y										
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0039	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0018	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0052	None Detected	N.D.	None	
Wall		Rubber, Brown baseboards			A	Y		100			%	V0028	None Detected	N.D.	None	
Wall		Rubber, Brown baseboards			A	Y		100			%	V0028	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F
Wall		Mastic, Brown, Brown baseboards		Rubber	D	N		100			%	V0013	None Detected	N.D.	None	
Wall		Mastic, Brown, Brown baseboards		Rubber	D	N		100			%	V0013	None Detected	N.D.	None	

Client: Halton District School Board
Location: #105 : Classroom / Storage
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 105
Last Re-Assessment: 0000-00-00

Area (sqft): 880

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	1760		SF	L0005	Light beige			Pb: 0.0043 %	No

Client: Halton District School Board
Location: #105 : Classroom / Storage
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 105
Last Re-Assessment: 0000-00-00

Area (sqft): 880

MERCURY										
Component	Quantity	Unit	Sample	Hazard						
Light Fixture ¹	16	EA	V0000							

1 - LEDs



ALL DATA REPORT



Client: Halton District School Board
Location: #106 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 106
Last Re-Assessment: 0000-00-00

Area (sqft): 880

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Duct		Not Insulated			C	N										
Floor		Mastic, Black, 12x12 Cream with maroon		Vinyl Floor Tile	D	N		100			%	V0009	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige fleck			A	Y		100			%	V0004	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other		Precast Refractory Brick, Kiln			D	N		1(7)			EA	V9500	Presumed Asbestos		Presumed Asbestos	NF
Other	Sink	Not Insulated			A	Y										
Other	Window	Caulking, Black			A	Y		40(7)			LF	V0015	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Piping		Fibreglass			C	Y										
Structure		Concrete (precast)			C	Y										
Structure		Concrete (precast)			C	N										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0039	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0018	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	
Wall		Rubber, Brown baseboards			A	Y		100			%	V0028	None Detected	N.D.	None	
Wall		Mastic, Brown, Brown baseboards		Rubber	D	N		100			%	V0013	None Detected	N.D.	None	

Client: Halton District School Board
Location: #106 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 106
Last Re-Assessment: 0000-00-00

Area (sqft): 880

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	1760		SF	V0005	Light beige			Pb: 0.0043 %	No

Client: Halton District School Board
Location: #106 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 106
Last Re-Assessment: 0000-00-00

Area (sqft): 880

MERCURY					
Component	Quantity	Unit	Sample	Hazard	
Light Fixture ¹	16	EA	V0000		

1 - LEDs

Client: Halton District School Board
Location: #107 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 107
Last Re-Assessment: 0000-00-00

Area (sqft): 815

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Mastic, Black		Vinyl Floor Tile	D	N		815			SF	S0056ABC	None Detected	N.D.	None	
Floor		Mastic			D	N		815(7)			SF	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Vinyl Floor Tile, 12x12 White/beige with beige flecks			A	Y		100			%	V0033	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 9x9		Carpet	D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Mechanical Equipment		None Found														
Other	Window	Caulking, Grey			A	Y		100			%	V0014	None Detected	N.D.	None	
Piping		Fibreglass			C	Y										
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	S0016E	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0052	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F
Wall		Vermiculite			D	N		100(7)			%	S0050A	Suspect Material		Presumed Asbestos	F

Client: Halton District School Board
Location: #107 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 107
Last Re-Assessment: 0000-00-00

Area (sqft): 815

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	1760		SF	V0005	Light beige			Pb: 0.0043 %	No

Client: Halton District School Board
Location: #107 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 107
Last Re-Assessment: 0000-00-00

Area (sqft): 815

MERCURY					
Component	Quantity	Unit	Sample	Hazard	
Light Fixture ¹		16	EA	V0000	

1 - LEDs

Client: Halton District School Board
 Location: #108 : Classroom
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 108
 Last Re-Assessment: 0000-00-00

Area (sqft): 815

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Mastic, Black, 9x9 Beige with white and brown streaks		Vinyl Floor Tile	D	N		100			%	V0002	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 9x9 Beige with white and brown streaks			A	Y		815(7)			SF	V0001	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Mechanical Equipment		None Found														
Other	Window	Caulking, Grey			A	Y		100			%	V0014	None Detected	N.D.	None	
Piping		Fibreglass			C	Y										
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0038	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

Client: Halton District School Board
 Location: #108 : Classroom
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 108
 Last Re-Assessment: 0000-00-00

Area (sqft): 815

PAINT											
System	Item	Good	Poor	Unit	Sample	Sample Description				Amount	Hazard
Wall	Concrete (precast)	1760		SF	V0005	Light beige				Pb: 0.0043 %	No

Client: Halton District School Board
 Location: #108 : Classroom
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 108
 Last Re-Assessment: 0000-00-00

Area (sqft): 815

MERCURY					
Component	Quantity	Unit	Sample	Hazard	
Light Fixture ¹	16	EA	V0000		

1 - LEDs

Client: Halton District School Board
Location: #109 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 109
Last Re-Assessment: 0000-00-00

Area (sqft): 815

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Mastic, Black, 9x9 Beige with white and brown streaks		Vinyl Floor Tile	D	N		100			%	V0002	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 9x9 Beige with white and brown streaks			A	Y		815(7)			SF	V0001	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Mechanical Equipment		None Found														
Other	Sink	Mastic, Gold			A	Y		2(7)			EA	S0049B	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other	Window	Caulking, Grey			A	Y		100			%	V0014	None Detected	N.D.	None	
Piping		Fibreglass			C	Y										
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0038	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

Client: Halton District School Board
Location: #109 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 109
Last Re-Assessment: 0000-00-00

Area (sqft): 815

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	1760		SF	V0005	Light beige			Pb: 0.0043 %	No

Client: Halton District School Board
Location: #109 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 109
Last Re-Assessment: 0000-00-00

Area (sqft): 815

MERCURY					
Component	Quantity	Unit	Sample	Hazard	
Light Fixture ¹		16	EA	V0000	

1 - LEDs

Client: Halton District School Board
 Location: #110 : Classroom
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 110
 Last Re-Assessment: 0000-00-00

Area (sqft): 700

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Mastic, Black, 12x12 Light beige with beige flecks		Vinyl Floor Tile	D	N		100			%	V0010	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Cream/wheat with purple fleck			A	Y		100			%	V0034	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Light beige with beige flecks			A	Y		100			%	V0029	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		Fibreglass			C	Y										
Structure		Masonry			C	Y										
Structure		Paint, Concrete block			C	Y		100			%	V0017	None Detected	N.D.	None	
Structure		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0040	None Detected	N.D.	None	
Wall		Plaster, Textured			C	Y		100			%	V0036	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	S0017E	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0053	None Detected	N.D.	None	
Wall		Rubber, Black baseboards			A	Y		100			%	V0041	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	

Client: Halton District School Board
 Location: #110 : Classroom
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 110
 Last Re-Assessment: 0000-00-00

Area (sqft): 700

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard		
Wall	Concrete (precast)	1200		SF	V0008	Light cream	Pb: 0.15 %	Lead (High)		

Client: Halton District School Board
 Location: #110 : Classroom
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 110
 Last Re-Assessment: 0000-00-00

Area (sqft): 700

MERCURY					
Component	Quantity	Unit	Sample	Hazard	
Light Fixture ¹	16		V0000		

1 - LEDs

Client: Halton District School Board
Location: #111 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 111
Last Re-Assessment: 0000-00-00

Area (sqft): 700

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Carpet			A	Y										
Floor		Mastic, Black, and levelling		Vinyl Floor Tile	D	N		100			%	S0059ABC	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Light beige with beige flecks			A	Y		100			%	V0029	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		Fibreglass			C	Y										
Structure		Masonry			C	Y										
Structure		Paint, Concrete block			C	Y		100			%	V0017	None Detected	N.D.	None	
Structure		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0040	None Detected	N.D.	None	
Wall		Plaster, Textured			C	Y		100			%	V0036	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	S0017D	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0053	None Detected	N.D.	None	
Wall		Rubber, Black baseboards			A	Y		100			%	V0041	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	
Wall	Door	Caulking			A	Y						S0063B	None Detected	N.D.	None	

Client: Halton District School Board
Location: #111 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 111
Last Re-Assessment: 0000-00-00

Area (sqft): 700

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	1200		SF	V0008	Light cream			Pb: 0.15 %	Lead (High)

Client: Halton District School Board
Location: #111 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 111
Last Re-Assessment: 0000-00-00

Area (sqft): 700

MERCURY										
Component	Quantity	Unit	Sample	Hazard						
Light Fixture ¹	16		V0000							

1 - LEDs

Client: Halton District School Board

Site: Elementary Schools

Building Name: Kilbride Public School

ALL DATA REPORT

Location: #111 : Classroom

Floor: 1

Room #: 111

Area (sqft): 700

Survey Date: 2024-08-07

Last Re-Assessment: 0000-00-00

Component	PCB				Sample Description	Amount	PCB
	Good	Poor	Unit	Sample			
Caulking	100		%	P0001		157 mg/kg	Yes

Client: Halton District School Board
Location: #112 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 112
Last Re-Assessment: 0000-00-00

Area (sqft): 700

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile and Mastic, 12x12 white		Carpet	D	N						S0061A	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Floor		Carpet			A	Y										
Floor		Mastic, Black, 12x12 Light beige with beige flecks		Vinyl Floor Tile	D	N		100			%	V0010	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Light beige with beige flecks			A	Y		100			%	V0029	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		Fibreglass			C	Y										
Structure		Masonry			C	Y										
Structure		Paint, Concrete block			C	Y		100			%	V0017	None Detected	N.D.	None	
Structure		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Plaster, Textured			C	Y		100			%	V0036	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0053	None Detected	N.D.	None	
Wall		Rubber, Black baseboards			A	Y		100			%	V0041	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	
Wall	Bulkhead	Drywall and joint compound			C	Y		100			%	V0040	None Detected	N.D.	None	

Client: Halton District School Board
Location: #112 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 112
Last Re-Assessment: 0000-00-00

Area (sqft): 700

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard		
Wall	Concrete (precast)	1200		SF	L0008	Light cream	Pb: 0.15 %	Lead (High)		

Client: Halton District School Board
Location: #112 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 112
Last Re-Assessment: 0000-00-00

Area (sqft): 700

MERCURY					
Component	Quantity	Unit	Sample	Hazard	
Light Fixture ¹	16		V0000		

1 - LEDs

Client: Halton District School Board

Site: Elementary Schools

Building Name: Kilbride Public School

Location: #112 : Classroom

Floor: 1

Survey Date: 2024-08-07

Room #: 112

Area (sqft): 700

Last Re-Assessment: 0000-00-00

Component	PCB				Sample Description	Amount	PCB
	Good	Poor	Unit	Sample			
Caulking	100		%	V0001		157 mg/kg	Yes

Client: Halton District School Board
Location: #113 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 113-A
Last Re-Assessment: 0000-00-00

Area (sqft): 1150

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wide fissures			C	Y		100			%	V0043	None Detected	N.D.	None	
Duct		Not Insulated			C	Y										
Floor		Ceramic Tiles			A	Y										
Floor		Mastic, Black, 12x12 Light beige with beige flecks		Vinyl Floor Tile	D	N		100			%	V0010	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Light beige with beige flecks			A	Y		100			%	V0029	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		Fibreglass			C	Y										
Structure		Masonry			C	Y										
Structure		Paint, Concrete block			C	Y		100			%	V0017	None Detected	N.D.	None	
Structure		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0040	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	S0017FG	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0053	None Detected	N.D.	None	
Wall		Rubber, Black baseboards			A	Y		100			%	V0041	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	

Client: Halton District School Board
Location: #114 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 114
Last Re-Assessment: 0000-00-00

Area (sqft): 700

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile and Mastic, 12x12 white		Carpet	D	N						S0061B	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Floor		Carpet			A	Y										
Floor		Mastic, Black, 12x12 Light beige with beige flecks		Vinyl Floor Tile	D	N		100			%	V0010	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Light beige with beige flecks			A	Y		100			%	V0029	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		Fibreglass			C	Y										
Structure		Masonry			C	Y										
Structure		Paint, Concrete block			C	Y		100			%	V0017	None Detected	N.D.	None	
Structure		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0040	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0053	None Detected	N.D.	None	
Wall		Rubber, Black baseboards			A	Y		100			%	V0041	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	

Client: Halton District School Board
Location: #114 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 114
Last Re-Assessment: 0000-00-00

Area (sqft): 700

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	1400		SF	L0006	Light pink			Pb: 0.14 %	Lead (High)

Client: Halton District School Board
Location: #114 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 114
Last Re-Assessment: 0000-00-00

Area (sqft): 700

MERCURY					
Component	Quantity	Unit	Sample	Hazard	
Light Fixture ¹	16			V0000	

1 - LEDs

Client: Halton District School Board
 Location: #115 : Classroom
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 115
 Last Re-Assessment: 0000-00-00

Area (sqft): 330

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		None Found														
Floor		Carpet			A	Y										
Floor		Mastic, Black, 12x12 Light beige with beige flecks		Vinyl Floor Tile	D	N		100			%	V0010	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Light beige with beige flecks			A	Y		100			%	V0029	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 9x9		Carpet	D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Mechanical Equipment		None Found														
Piping ¹		Parging Cement	Fitting		C	N		7(7)			EA	V0048	Chrysotile	10-25%	Confirmed Asbestos	F
Piping		Sweatwrap			C	N		4(7)			LF	V0023	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		None Found														
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall ²		Cement Product, Transite			C	Y		80(7)			SF	V0025	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall		Paint, Concrete block			A	Y		100			%	S0016F	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0052	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

1 - In closet

2 - Above window

Client: Halton District School Board
 Location: #115 : Classroom
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 115
 Last Re-Assessment: 0000-00-00

Area (sqft): 330

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	1760		SF	V0005	Light beige			Pb: 0.0043 %	No

Client: Halton District School Board
 Location: #115 : Classroom
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 115
 Last Re-Assessment: 0000-00-00

Area (sqft): 330

MERCURY										
Component	Quantity	Unit	Sample	Hazard						
Light Fixture ¹	8			V0000						



ALL DATA REPORT



1 - LEDs

Client: Halton District School Board
 Location: #116 : Library
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 116-A-B-C-D
 Last Re-Assessment: 0000-00-00

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with dense width wide fissures			C	Y		100			%	V0042	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wide fissures			C	Y		100			%	V0043	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y		100			%	V0044	None Detected	N.D.	None	
Ceiling ¹	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 random fissures			C	Y		100			%	V0045	None Detected	N.D.	None	
Duct	Not Accessible															
Floor		Vinyl Floor Tile and Mastic, 9x9 red and beige		Carpet	D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Floor		Carpet			A	Y										
Floor		Mastic, Black, 12x12 Light beige with beige flecks		Vinyl Floor Tile	D	N		100			%	V0010	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Light beige with beige flecks			A	Y		100			%	V0029	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 White/beige with beige flecks			A	Y		100			%	V0033	None Detected	N.D.	None	
Mechanical Equipment	Not Accessible															
Piping ²		Parging Cement	Fitting		C	Y		3(7)			EA	V0047	Chrysotile	25-50%	Confirmed Asbestos	F
Piping ³		Parging Cement	Fitting		C	Y		3(7)			EA	V0048	Chrysotile	10-25%	Confirmed Asbestos	F
Piping ⁴		Parging Cement	Fitting		C	N		7(7)			EA	V0048	Chrysotile	10-25%	Confirmed Asbestos	F
Piping ⁵		Sweatwrap			C	Y		3(7)			LF	V0023	Chrysotile	50-75%	Confirmed Asbestos	F
Piping ⁶		Sweatwrap			C	N		10(7)			LF	V0023	Chrysotile	50-75%	Confirmed Asbestos	F
Piping	Not Accessible															
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Structure	Not Accessible															
Wall		Drywall and joint compound			A	Y		100			%	V0038	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F
Wall	Door	Caulking			A	Y		18(7)			LF	V0068	Chrysotile	0.5-5%	Confirmed Asbestos	NF

No access above ceiling- Height restrictions (15ft)

1 - 2002

2 - In 116

3 - In 116

4 - In 116C
5 - In 116
6 - In 116C

Client: Halton District School Board

Location: #116 : Library

Survey Date: 2024-08-07

Site: Elementary Schools

Floor: 1

Building Name: Kilbride Public School

Room #: 116-A-B-C-D

Area (sqft): 0

Last Re-Assessment: 0000-00-00

MERCURY

Component	Quantity	Unit	Sample	Hazard
Light Fixture ¹	24		V0000	

No access above ceiling- Height restrictions (15ft)

1 - LEDs

Client: Halton District School Board

Location: #116 : Library

Survey Date: 2024-08-07

Site: Elementary Schools

Floor: 1

Building Name: Kilbride Public School

Room #: 116-A-B-C-D

Area (sqft): 0

PCB

Component	Good	Poor	Unit	Sample	Sample Description	Amount	PCB
Caulking	100		%	V0004		0.7 mg/kg	No

No access above ceiling- Height restrictions (15ft)

Client: Halton District School Board
Location: #117 : Washroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 117
Last Re-Assessment: 0000-00-00

Area (sqft): 30

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y						V0000	Non-Asbestos		None	
Duct		Not Insulated			C	N										
Floor		Mastic, Black, 12x12 Light beige with beige flecks		Vinyl Floor Tile	D	N		100			%	V0010	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Light beige with beige flecks			A	Y		100			%	V0029	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Structure		Concrete (precast)			C	N										
Structure		Caulking, Siporex			C	N		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

Client: Halton District School Board
Location: #118 : Washroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 118
Last Re-Assessment: 0000-00-00

Area (sqft): 30

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		None Found														
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

Client: Halton District School Board
Location: #119 : Washroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 119
Last Re-Assessment: 0000-00-00

Area (sqft): 30

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		Parging Cement	Fitting		C	Y		2(7)			EA	V0048	Chrysotile	10-25%	Confirmed Asbestos	F
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

Client: Halton District School Board
Location: #120 : Mechanical Room
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 120-A
Last Re-Assessment: 0000-00-00

Area (sqft): 300

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Mastic, Red, silicone			A	Y						V0000	Non-Asbestos			None
Duct		Not Insulated			C	Y										
Floor		Concrete (poured)			A	Y										
Mechanical Equipment	Boiler	Fibreglass			A	Y										
Mechanical Equipment	Domestic Hot Water Tank	Fibreglass			A	Y										
Other ¹		Tar			C	Y		33			%	S0073ABC	None Detected	N.D.	None	
Piping		Fibreglass			C	Y										
Piping		Parging Cement	Fitting		C	Y		18(7)			EA	V0047	Chrysotile	25-50%	Confirmed Asbestos	F
Piping		Parging Cement	Fitting		C	Y		5(7)			EA	V0048	Chrysotile	10-25%	Confirmed Asbestos	F
Piping		Sweatwrap			C	Y		60(7)			LF	V0023	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Not Insulated			C	Y										
Piping		Gasket, Red			A	Y						S0072ABC	None Detected	N.D.	None	
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	S0016G	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

1 - On walls from roof penetration

Client: Halton District School Board
Location: #120 : Mechanical Room
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 120-A
Last Re-Assessment: 0000-00-00

Area (sqft): 300

PAINT											
System	Item	Good	Poor	Unit	Sample	Sample Description				Amount	Hazard
Floor	Concrete (poured)	290	10	SF	L0001	Grey				Pb: 0.40 %	Lead (High)
Wall	Concrete (precast)	600		SF	L0002	Light green				Pb: 0.29 %	Lead (High)
Piping	Metal	8		SF	L0003	Blue				Pb: 0.23 %	Lead (High)
Piping	Metal	45		SF	L0004	Yellow				Pb: 0.011 %	Lead (Low)
Mechanical Equipment	Metal	40		SF	L0015	White on metal cushion tank				Pb: 0.052 %	Lead (Low)

Client: Halton District School Board
Location: #120 : Mechanical Room
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 120-A
Last Re-Assessment: 0000-00-00

Area (sqft): 300

PB PRODUCTS					
Component	Quantity	Unit	Sample	Hazard	
Batteries (other)	1	EA	V9000	Yes	

Client: Halton District School Board

Location: #120 : Mechanical Room

Survey Date: 2024-08-07

Site: Elementary Schools

Floor: 1

Building Name: Kilbride Public School

Room #: 120-A

Area (sqft): 300

Last Re-Assessment: 0000-00-00

MERCURY

Component	Quantity	Unit	Sample	Hazard
Thermostat	1	EA	V9000	Yes

Client: Halton District School Board

Location: #120 : Mechanical Room

Survey Date: 2024-08-07

Site: Elementary Schools

Floor: 1

Building Name: Kilbride Public School

Room #: 120-A

Area (sqft): 300

Last Re-Assessment: 0000-00-00

PCB

Component	Good	Poor	Unit	Sample	Sample Description	Amount	PCB
Transformer	1		EA	V0000			No

Client: Halton District School Board
 Location: #121 : Office
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 121
 Last Re-Assessment: 0000-00-00

Area (sqft): 110

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y		100			%	V0044	None Detected	N.D.	None	
Duct		Not Insulated			C	Y										
Floor		Mastic			D	N		110			SF	V0056	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 White/beige with beige flecks			A	Y		100			%	V0033	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		Parging Cement	Fitting		C	Y		4(7)			EA	V0048	Chrysotile	10-25%	Confirmed Asbestos	F
Piping		Sweatwrap			C	N		5(7)			LF	V0023	Chrysotile	50-75%	Confirmed Asbestos	F
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Drywall and joint compound			C	Y		100			%	V0038	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

Client: Halton District School Board
 Location: #121 : Office
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 121
 Last Re-Assessment: 0000-00-00

Area (sqft): 110

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	1760		SF	V0005	Light beige			Pb: 0.0043 %	No

Client: Halton District School Board
 Location: #121 : Office
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 121
 Last Re-Assessment: 0000-00-00

Area (sqft): 110

PB PRODUCTS					
Component	Quantity	Unit	Sample	Hazard	
Batteries In Emer. Lights	1	EA	V9500	Presumed	

Client: Halton District School Board
 Location: #121 : Office
 Survey Date: 2024-08-07

Site: Elementary Schools
 Floor: 1

Building Name: Kilbride Public School
 Room #: 121
 Last Re-Assessment: 0000-00-00

Area (sqft): 110

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Fixture ¹	2		V0000	

1 - LEDs

Client: Halton District School Board
Location: #122 : Boy's Washroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 122
Last Re-Assessment: 0000-00-00

Area (sqft): 220

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y		100			%	V0044	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Structure		Concrete (precast)			C	N										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

Client: Halton District School Board
Location: #123 : Girl's Washroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 123
Last Re-Assessment: 0000-00-00

Area (sqft): 220

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y		100			%	V0044	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Structure		Concrete (precast)			C	N										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0052	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F

Client: Halton District School Board
Location: #124 : Supply Room
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 124
Last Re-Assessment: 0000-00-00

Area (sqft): 570

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Duct		None Found														
Floor		Mastic, Black, 12x12 White/green with directional fleck		Vinyl Floor Tile	D	N		570(7)			SF	V0011	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile, 12x12 White/green with directional fleck			A	Y		570(7)			SF	V0035	Chrysotile	5-10%	Confirmed Asbestos	NF
Mechanical Equipment		None Found														
Structure		Masonry			C	Y										
Structure		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Structure		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0040	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Rubber, Black baseboards			A	Y		100			%	V0041	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	

Client: Halton District School Board
Location: #125 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 125-A
Last Re-Assessment: 0000-00-00

Area (sqft): 450

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wide fissures			C	Y		100			%	V0043	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Vinyl Floor Tile and Mastic, 12x12 white, in radiator			D	N						S0061C	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile, 12x12 Cream/wheat with purple fleck			A	Y		100			%	V0034	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Sink	Not Insulated			A	Y										
Structure		Masonry			C	N										
Structure		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Structure		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0040	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0053	None Detected	N.D.	None	
Wall		Rubber, Black baseboards			A	Y		100			%	V0041	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	

Client: Halton District School Board
Location: #125 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 125-A
Last Re-Assessment: 0000-00-00

Area (sqft): 450

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	250		SF	V0007	Cream			Pb: 0.13 %	Lead (High)

Client: Halton District School Board
Location: #125 : Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 125-A
Last Re-Assessment: 0000-00-00

Area (sqft): 450

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Fixture ¹	16		V0000	

1 - LEDs

Client: Halton District School Board
Location: #126 : Office / Washroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 126-A
Last Re-Assessment: 0000-00-00

Area (sqft): 125

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wide fissures			C	Y		100			%	V0043	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Vinyl Floor Tile and Mastic, 12x12 beige with grey and brown streaks			A	Y		125(7)			SF	S0060ABC	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Floor		Mastic, Black, 12x12 Dark beige with dark beige fleck		Vinyl Floor Tile	D	N		100			%	V0007	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige fleck			A	Y		100			%	V0030	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Window	Putty			A	Y		20(7)			LF	S0064B	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Piping ¹		Parging Cement	Fitting		C	N		8(7)			EA	V0026	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Tar	Straight		C	N						S0065ABC	None Detected	N.D.	None	
Structure		Masonry			C	N										
Structure		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Structure		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0053	None Detected	N.D.	None	
Wall		Rubber, Black baseboards			A	Y		100			%	V0041	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	
Wall	Door	Caulking			A	Y						S0063A	None Detected	N.D.	None	
Wall	Expansion Joint	Caulking, corners			A	Y						V0063	None Detected	N.D.	None	

1 - In 126A

Client: Halton District School Board
Location: #126 : Office / Washroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 126-A
Last Re-Assessment: 0000-00-00

Area (sqft): 125

PAINT											
System	Item	Good	Poor	Unit	Sample	Sample Description				Amount	Hazard
Wall	Concrete (precast)	250		SF	L0007	Cream				Pb: 0.13 %	Lead (High)

Client: Halton District School Board
Location: #126 : Office / Washroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 126-A
Last Re-Assessment: 0000-00-00

Area (sqft): 125

PCB								
Component	Good	Poor	Unit	Sample	Sample Description	Amount	PCB	
Caulking	100		%	V0001			157 mg/kg	Yes

Client: Halton District School Board
Location: #127 : Storage / Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 127-A-B
Last Re-Assessment: 0000-00-00

Area (sqft): 550

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wide fissures			C	Y		100			%	V0043	None Detected	N.D.	None	
Ceiling ¹	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 textured			C	Y						V0000	Non-Asbestos		None	
Duct		Not Insulated			C	N										
Floor		Vinyl Floor Tile and Mastic, 12x12 grey with beige fleck			A	Y		40			SF	S0077ABC	None Detected	N.D.	None	
Floor		Terrazzo			A	Y										
Floor		Mastic, Black, 12x12 Light beige with beige flecks		Vinyl Floor Tile	D	N		100			%	V0010	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Light beige with beige flecks			A	Y		100			%	V0029	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Sink	Not Insulated			A	Y										
Piping		Fibreglass			C	N										
Piping		Parging Cement	Fitting		C	N		8(7)			EA	V0026	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement	Fitting		C	N		4(7)			EA	V0046	Chrysotile	25-50%	Confirmed Asbestos	F
Structure		Masonry			C	Y										
Structure		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Structure		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0040	None Detected	N.D.	None	
Wall		Plaster, Textured			C	Y		100			%	V0036	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Rubber, Black baseboards			A	Y		100			%	V0041	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	

1 - Fibreglass

Client: Halton District School Board
Location: #127 : Storage / Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 127-A-B
Last Re-Assessment: 0000-00-00

Area (sqft): 550

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	1200		SF	V0008	Light cream			Pb: 0.15 %	Lead (High)

Client: Halton District School Board
Location: #127 : Storage / Corridor

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 127-A-B

Area (sqft): 550

Survey Date: 2024-08-07

Last Re-Assessment: 0000-00-00

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Fixture ¹	16		V0000	

1 - LEDs

Client: Halton District School Board
Location: #128 : Kitchen
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 128
Last Re-Assessment: 0000-00-00

Area (sqft): 720

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with dense width wide fissures			C	Y		100			%	V0042	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wide fissures			C	Y		100			%	V0043	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N						S0062ABC	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige flecks			A	Y		100			%	V0030	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Sink	Mastic, Gold			A	Y		2(7)			EA	S0049C	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Piping		Fibreglass			C	N										
Structure	Deck	Metal			C	N										
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	S0018D	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	

Client: Halton District School Board
Location: #128 : Kitchen
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 128
Last Re-Assessment: 0000-00-00

Area (sqft): 720

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Fixture ¹	16		V0000	

1 - LEDs

Client: Halton District School Board
Location: #129 : Equipment Storage
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 129
Last Re-Assessment: 0000-00-00

Area (sqft): 320

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	N										
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige flecks			A	Y		100			%	V0030	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Structure	Deck	Metal			C	N										
Wall		Masonry			A	Y										
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	

Client: Halton District School Board
Location: #130 : Equipment Storage
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 130
Last Re-Assessment: 0000-00-00

Area (sqft): 320

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	N										
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige flecks			A	Y		100			%	V0030	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Structure	Deck	Metal			C	N										
Wall		Masonry			A	Y										
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	

Client: Halton District School Board
Location: #131 : Equipment Storage
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 131
Last Re-Assessment: 0000-00-00

Area (sqft): 320

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	N										
Floor		Concrete (poured)			A	Y										
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Structure	Deck	Metal			C	N										
Wall		Masonry			A	Y										
Wall		Mortar, Concrete block			D	N	100			%	V0021	None Detected	N.D.	None		

Client: Halton District School Board
Location: #132 : Gymnasium
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 132
Last Re-Assessment: 0000-00-00

Area (sqft): 4000

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Floor Levelling Compound		Foam	D	N						S0069ABC	None Detected	N.D.	None	
Floor		Foam, sheeting, faux wood			A	Y						V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Other	Door	Caulking			A	Y	6(7)				LF	S0068B	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Piping		Fibreglass			C	Y										
Structure	Deck	Metal			C	Y										
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y	100			%	S0018FG	None Detected	N.D.	None		
Wall		Mortar, Concrete block			D	N	100			%	V0021	None Detected	N.D.	None		
Wall		Mortar, Exterior brick			D	N	100			%	V0054	None Detected	N.D.	None		

Client: Halton District School Board
Location: #133 : Storage
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 133-A
Last Re-Assessment: 0000-00-00

Area (sqft): 115

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with dense width wide fissures			C	Y		100			%	V0042	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wide fissures			C	Y		100			%	V0043	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige flecks			A	Y		100			%	V0030	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Structure	Deck	Metal			C	N										
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0018	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0054	None Detected	N.D.	None	

Client: Halton District School Board
Location: #134 : Changeroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 134
Last Re-Assessment: 0000-00-00

Area (sqft): 400

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0039	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Structure	Deck	Metal			C	N										
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0018	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0054	None Detected	N.D.	None	

Client: Halton District School Board
Location: #135 : Washroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 135
Last Re-Assessment: 0000-00-00

Area (sqft): 400

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0039	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Structure	Deck	Metal			C	N										
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0018	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	

Client: Halton District School Board
Location: #136 : Changeroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 136-A
Last Re-Assessment: 0000-00-00

Area (sqft): 400

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0039	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Structure	Deck	Metal			C	N										
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0018	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	

Client: Halton District School Board
Location: #137 : Washroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 137-A
Last Re-Assessment: 0000-00-00

Area (sqft): 400

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0039	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Ceramic Tiles			A	Y										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Structure	Deck	Metal			C	N										
Wall		Masonry			A	Y										
Wall		Ceramic Tiles			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	S0018E	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	

Client: Halton District School Board
Location: #138 : Gym Office
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 138-A
Last Re-Assessment: 0000-00-00

Area (sqft): 115

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with dense width wide fissures			C	Y		100			%	V0042	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wide fissures			C	Y		100			%	V0043	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Ceramic Tiles			A	Y										
Floor		Terrazzo			A	Y										
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige flecks			A	Y		100			%	V0030	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Structure	Deck	Metal			C	N										
Wall		Masonry			A	Y										
Wall		Ceramic Tiles			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0018	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	

Client: Halton District School Board
Location: #139 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 139
Last Re-Assessment: 0000-00-00

Area (sqft): 250

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wide fissures			C	Y		100			%	V0043	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y		100			%	V0044	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Ceramic Tiles			A	Y										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		Fibreglass			C	N										
Piping		Not Insulated			C	N										
Structure	Deck	Metal			C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0039	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	V0018	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	

Client: Halton District School Board
Location: #140 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 140-A-B-C
Last Re-Assessment: 0000-00-00

Area (sqft): 850

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wide fissures			C	Y		100			%	V0043	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y		100			%	V0044	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Ceramic Tiles			A	Y										
Floor		Terrazzo			A	Y						V0070	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Door	Caulking, door 11			A	Y		100(7)			LF	S0068A	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other	Window	Putty			A	Y		50(7)			LF	S0066C	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Piping		Fibreglass			C	N										
Piping		Not Insulated			C	N										
Structure	Deck	Metal			C	N										
Wall		Drywall and joint compound			A	Y		100			%	V0039	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	V0018	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0053	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0054	None Detected	N.D.	None	
Wall ¹		Vermiculite			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F

1 - 1967 Wall

Client: Halton District School Board
Location: #140 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 140-A-B-C
Last Re-Assessment: 0000-00-00

Area (sqft): 850

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete Block				L0014	cream/blue			Pb: 0.0024 %	No

Client: Halton District School Board
Location: #140 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 140-A-B-C
Last Re-Assessment: 0000-00-00

Area (sqft): 850

MERCURY					
Component	Quantity	Unit	Sample	Hazard	
Light Fixture ¹	18	EA	V0000		

1 - LEDs

Client: Halton District School Board
Location: #141 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 141-A
Last Re-Assessment: 0000-00-00

Area (sqft): 370

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with dense width wide fissures			C	Y		100			%	V0042	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wide fissures			C	Y		100			%	V0043	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y		100			%	V0044	None Detected	N.D.	None	
Ceiling	Soffit	Plaster, Textured, exterior Door #3			C	Y		160(7)			SF	V0037	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct		Not Insulated			C	N										
Floor		Terrazzo			A	Y						S0070AB	None Detected	N.D.	None	
Mechanical Equipment		Not Insulated														
Other	Window	Putty			A	Y		55(7)			LF	S0064AC	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Piping		Fibreglass			C	N										
Piping		Parging Cement	Fitting		C	N		5(7)			EA	V0026	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement	Fitting		C	N		5(7)			EA	V0046	Chrysotile	25-50%	Confirmed Asbestos	F
Structure		Masonry			C	N										
Structure		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0053	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F
Wall	Door	Caulking			A	Y						S0063C	None Detected	N.D.	None	

Client: Halton District School Board
Location: #141 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 141-A
Last Re-Assessment: 0000-00-00

Area (sqft): 370

MERCURY						
Component			Quantity		Unit	Sample
Light Fixture ¹			8		EA	V0000

1 - LEDs

Client: Halton District School Board
Location: #141 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 141-A
Last Re-Assessment: 0000-00-00

Area (sqft): 370

PCB							
Component	Good	Poor	Unit	Sample	Sample Description	Amount	PCB
Caulking	100	%		V0001		157 mg/kg	Yes

Client: Halton District School Board
Location: #142 : Cubby Area
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 142
Last Re-Assessment: 0000-00-00

Area (sqft): 180

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with dense width wide fissures			C	Y		100			%	V0042	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wide fissures			C	Y		100			%	V0043	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y		100			%	V0044	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Terrazzo			A	Y										
Mechanical Equipment		Not Insulated														
Piping		Fibreglass			C	N										
Piping		Parging Cement	Fitting		C	N		4(7)			EA	V0026	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement	Fitting		C	N		3(7)			EA	V0046	Chrysotile	25-50%	Confirmed Asbestos	F
Structure		Masonry			C	N										
Structure		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F

Client: Halton District School Board
Location: #143 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 143
Last Re-Assessment: 0000-00-00

Area (sqft): 750

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Concrete (poured)			A	Y										
Mechanical Equipment		None Found														
Other	Door	Caulking, door 1			A	Y						S0057ABC	None Detected	N.D.	None	
Other	Door	Putty, window, Door 1			A	Y		55(7)			LF	S0055ABC	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Piping		Fibreglass			C	Y										
Piping		Parging Cement	Fitting		C	N		14(7)			EA	V0047	Chrysotile	25-50%	Confirmed Asbestos	F
Piping		Parging Cement	Fitting		C	N		23(7)			EA	V0048	Chrysotile	10-25%	Confirmed Asbestos	F
Piping		Parging Cement	Fitting		C	N		100(7)			%	V0026	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement	Fitting		C	N		100(7)			%	V0046	Chrysotile	25-50%	Confirmed Asbestos	F
Piping		Sweatwrap			C	N		120(7)			LF	V0023	Chrysotile	50-75%	Confirmed Asbestos	F
Structure		Concrete (precast)			C	Y										
Structure		Masonry			C	N										
Structure		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Structure		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Cement Product, Transite board above exterior door 1			C	N		90(7)			SF	V9000	Confirmed Asbestos		Confirmed Asbestos	NF
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	V0017	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0020	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0052	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0053	None Detected	N.D.	None	
Wall		Rubber, Black baseboards			A	Y		100			%	V0041	None Detected	N.D.	None	
Wall		Vermiculite, 1967			D	N		100(7)			%	V0022	Actinolite	25-50%	Confirmed Asbestos	F
Wall		Vermiculite, 1959			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	V0012	None Detected	N.D.	None	

Client: Halton District School Board
Location: #143 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 143
Last Re-Assessment: 0000-00-00

Area (sqft): 750

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Wall	Concrete (precast)	250		SF	V0007	Cream			Pb: 0.13 %	Lead (High)
Wall	Concrete (precast)	1500		SF	L0016	Cream on block			Pb: 0.00043 %	No

Client: Halton District School Board

Site: Elementary Schools

Building Name: Kilbride Public School

Location: #143 : Corridor

Floor: 1

Room #: 143

Area (sqft): 750

Survey Date: 2024-08-07

MERCURY

Component	Quantity	Unit	Sample	Hazard
Light Fixture ¹	18	EA	V0000	

1 - LEDs

Client: Halton District School Board

Site: Elementary Schools

Building Name: Kilbride Public School

Location: #143 : Corridor

Floor: 1

Room #: 143

Area (sqft): 750

Survey Date: 2024-08-07

PCB

Component	Good	Poor	Unit	Sample	Sample Description	Amount	PCB
Caulking	100		%	P0004		0.7 mg/kg	No
Caulking	100		%	V0001		157 mg/kg	Yes

Client: Halton District School Board
Location: #144 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 144
Last Re-Assessment: 0000-00-00

Area (sqft): 1080

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Concrete (poured)			A	Y										
Mechanical Equipment		None Found														
Piping		Fibreglass			C	Y										
Piping		Sweatwrap			C	N		120(7)			LF	V0023	Chrysotile	50-75%	Confirmed Asbestos	F
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0019	None Detected	N.D.	None	

Client: Halton District School Board
Location: #144 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 144
Last Re-Assessment: 0000-00-00

Area (sqft): 1080

MERCURY						
Component		Quantity		Unit	Sample	Hazard
Light Fixture ¹		18		EA	V0000	

1 - LEDs

Client: Halton District School Board
Location: #145 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 145-A
Last Re-Assessment: 0000-00-00

Area (sqft): 340

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y						V0000	Non-Asbestos			None
Duct		Not Insulated			C	Y										
Floor		Terrazzo			A	Y						S0070C	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Other	Door	Caulking, door 2			A	Y		68(7)			LF	S0068C	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other	Window	Putty			A	Y		50(7)			LF	S0066AB	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Piping		Fibreglass			C	Y										
Structure		Concrete (precast)			C	Y										
Structure		Caulking, Siporex			C	Y		100			%	V0024	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	V0039	None Detected	N.D.	None	
Wall		Masonry			A	Y										
Wall		Paint, Concrete block			A	Y		100			%	V0018	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	

Client: Halton District School Board
Location: #145 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 145-A
Last Re-Assessment: 0000-00-00

Area (sqft): 340

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Ceiling	Drywall and joint compound	340			L0009	Beige			Pb: 0.0024 %	No

Client: Halton District School Board
Location: #145 : Corridor
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 145-A
Last Re-Assessment: 0000-00-00

Area (sqft): 340

MERCURY					
Component	Quantity	Unit	Sample	Hazard	
Light Fixture ¹	8	EA	V0000		

1 - LEDs

Client: Halton District School Board
Location: #146 : Stairwell
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1/2

Building Name: Kilbride Public School
Room #: 146
Last Re-Assessment: 0000-00-00

Area (sqft): 100

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		None Found														
Floor		Concrete (poured)			A	Y										
Mechanical Equipment		None Found														
Piping		Fibreglass			C	Y										
Structure	Deck	Metal			C	Y										
Wall		Masonry			A	Y										
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	

Client: Halton District School Board
Location: #147 : Mezzanine Mechanical Room
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 147
Last Re-Assessment: 0000-00-00

Area (sqft): 1000

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Concrete (poured)			A	Y										
Mechanical Equipment		Fibreglass			A	Y										
Piping		Fibreglass			A	Y										
Structure	Deck	Metal			C	Y										
Wall		Masonry			A	Y										
Wall		Mortar, Concrete block			D	N		100			%	V0021	None Detected	N.D.	None	

Client: Halton District School Board
Location: #148 : JK / SK Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 116
Last Re-Assessment: 0000-00-00

Area (sqft): 1200

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y						V0000	Non-Asbestos		None	
Duct		Not Insulated			C	N										
Floor		Vinyl Sheet Flooring, Beige and blue with speckles			A	Y						V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y										
Mechanical Equipment		None Found														
Other	Sink	Not Insulated			A	Y										
Piping		Fibreglass			C	N										
Piping		Not Insulated			C	N										
Structure	Deck	Metal			C	N										
Wall		Drywall and joint compound			A	Y						V0000	Non-Asbestos		None	
Wall		Paint, Concrete block			A	Y						V0000	Non-Asbestos		None	
Wall		Mortar, Concrete block			D	N						V0000	Non-Asbestos		None	

Client: Halton District School Board
Location: #149 : JK / SK Classroom
Survey Date: 2024-08-07

Site: Elementary Schools
Floor: 1

Building Name: Kilbride Public School
Room #: 117
Last Re-Assessment: 0000-00-00

Area (sqft): 700

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y						V0000	Non-Asbestos		None	
Duct		Not Insulated			C	N										
Floor		Ceramic Tiles			A	Y										
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige flecks			A	Y						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile, 12x12 blue with blue flecks			A	Y						V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Other	Sink	Not Insulated			A	Y										
Piping		Fibreglass			C	N										
Piping		Not Insulated			C	N										
Structure	Deck	Metal			C	N										
Wall		Drywall and joint compound			A	Y						V0000	Non-Asbestos		None	
Wall		Paint			D	N						V0000	Non-Asbestos		None	
Wall		Mortar			D	N						V0000	Non-Asbestos		None	

Client: Halton District School Board
Location: #150 : Exterior 1967 Era
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Soffit	Plaster, Textured			C	Y		80(7)			SF	V0037	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Other		Caulking			A	Y		100(7)			%	V0051	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other		Caulking, White			A	Y		100(7)			%	V0027	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other	Door	Caulking, Grey			A	Y		60(7)			LF	S0074ABC	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other	Window	Caulking, Black			A	Y		100(7)			%	V0015	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other	Window	Caulking, White			A	Y		100(7)			%	V0027	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other	Window	Caulking			A	Y		100(7)			%	V0051	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F
Wall	Spandrel Panel	Styrofoam, library panels		Metal	D	N						V0000	Non-Asbestos		None	

Client: Halton District School Board
Location: #150 : Exterior 1967 Era
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

PAINT										
System	Item	Good	Poor	Unit	Sample	Sample Description			Amount	Hazard
Other	Metal				V0010	blue, doors			Pb: 0.0018 %	No

Client: Halton District School Board
Location: #150 : Exterior 1967 Era
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

PCB										
Component	Good	Poor	Unit	Sample	Sample Description			Amount	PCB	
Caulking	100		%	P0002	composite, 1967			24 mg/kg	No	
Caulking	100		%	P0003	composite, 1959			0.2 mg/kg	No	

Client: Halton District School Board
Location: #151 : Exterior 1959 Era
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Other		Tar, Tar on canopy roof			C	Y		130			SF	S0075ABC	None Detected	N.D.	None	
Other		Tar, Tar on roof penetration above mechanical room			C	Y		10			SF	S0076ABC	None Detected	N.D.	None	
Other	Door	Caulking, Library window panels			A	Y		217(7)			LF	S0058ABC	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other ¹	Fascia	Cement Product			C	Y		100(7)			%	V0025	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall		Plaster, parging on foundation, outside library			A	Y						S0071ABC	None Detected	N.D.	None	
Wall		Cement Product, Door #1			C	Y		200(7)			SF	V9000	Confirmed Asbestos		Confirmed Asbestos	NF
Wall		Vermiculite			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	F
Wall		Vermiculite Investigation, Vermiculite Investigation, visible holes and cracks in masonry, exterior of library. No vermiculite observed			A	Y										
Wall	Spandrel Panel	Styrofoam			A	Y										

1 - Transite

Client: Halton District School Board
Location: #151 : Exterior 1959 Era
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

PAINT											
System	Item	Good	Poor	Unit	Sample	Sample Description				Amount	Hazard
Other	Metal	100		%	L0010	blue, door 1				Pb: 0.0018 %	No
Other	Wood	100		%	L0011	white on canopy beam				Pb: 0.97 %	Lead (High)
Other	Wood	100		%	L0012	brown on canopy deck				Pb: 0.26 %	Lead (High)

Client: Halton District School Board
Location: #152 : Exterior 1984 Era
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Other	Door	Caulking, Door 2			A	Y		100(7)			LF	S0067ABC	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other	Window	Caulking, Black			A	Y		100(7)			%	V0015	Chrysotile	0.5-5%	Confirmed Asbestos	NF

Client: Halton District School Board
Location: #152 : Exterior 1984 Era
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

PAINT											
System	Item	Good	Poor	Unit	Sample	Sample Description				Amount	Hazard
Ceiling	Drywall and joint compound				L0013	white on soffit, door 11				Pb: 0.0021 %	No
Other	Metal				V0010	blue, doors				Pb: 0.0018 %	No

Client: Halton District School Board
Location: #153 : Exterior 2009 Era
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Wall		Concrete Block			A	Y										

Client: Halton District School Board
Location: #158 : Roofs
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Other		Roofing material			C	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF

Era 1959, 1967, 1984, 2009

Client: Halton District School Board
Location: #1959 : 1959 Samples
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with dense width wide fissures			C	Y		100			%	S0042	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with width wise fissures			C	Y		100			%	S0043	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 pinhole with fleck			C	Y		100			%	S0044	None Detected	N.D.	None	
Ceiling ¹	Acoustic Tile	Ceiling Tiles (lay-in), 24x48 random fissures			C	Y		100			%	S0045	None Detected	N.D.	None	
Floor		Mastic, Black, 9x9 Beige with white and brown streaks		Vinyl Floor Tile	D	N		100			%	S0002	None Detected	N.D.	None	
Floor		Mastic, Black, 9x9 Green		Vinyl Floor Tile	D	N		100			%	S0003	None Detected	N.D.	None	
Floor		Mastic, Black, 12x12 Light green		Vinyl Floor Tile	D	N		100			%	S0008	None Detected	N.D.	None	
Floor		Mastic, Black, 12x12 Cream with maroon		Vinyl Floor Tile	D	N		100			%	S0009	None Detected	N.D.	None	
Floor		Mastic, Black, 12x12 Light beige		Vinyl Floor Tile	D	N		100			%	S0010	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 9x9 Beige with white and brown streaks			A	Y		100(7)			%	S0001	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile, 12x12 Light beige with beige flecks			A	Y		100			%	S0029	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 9x9 Green			A	Y		100(7)			%	S0031	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile, 12x12 Light green			A	Y		100			%	S0032	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 White/beige with beige flecks			A	Y		100			%	S0033	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige flecks			A	Y		100			%	S0030	None Detected	N.D.	None	
Other	Window	Caulking, Grey			A	Y		100			%	S0014	None Detected	N.D.	None	
Piping		Parging Cement	Fitting		C	N		100(7)			%	S0047	Chrysotile	25-50%	Confirmed Asbestos	F
Piping		Parging Cement	Fitting		C	N		100(7)			%	S0048	Chrysotile	10-25%	Confirmed Asbestos	F
Piping		Sweatwrap			C	N		100(7)			%	S0023	Chrysotile	50-75%	Confirmed Asbestos	F
Structure		Caulking, Siporex			C	Y		100			%	S0024	None Detected	N.D.	None	
Wall		Drywall and joint compound			A	Y		100			%	S0038	None Detected	N.D.	None	
Wall		Cement Product, Transite			C	Y		100(7)			%	S0025	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall		Paint, Concrete block			A	Y		100			%	S0016	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	S0019	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	V0052	None Detected	N.D.	None	

1 - 2002

Client: Halton District School Board
Location: #1967 : 1967 Samples
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Soffit	Plaster, Textured			C	Y		100(7)			%	S0037	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Floor		Mastic, Black, 12x12 Cream		Vinyl Floor Tile	D	N		100			%	S0006	None Detected	N.D.	None	
Floor		Mastic, Black, 12x12 Dark beige with dark beige fleck		Vinyl Floor Tile	D	N		100			%	S0007	None Detected	N.D.	None	
Floor		Mastic, Black, 12x12 White		Vinyl Floor Tile	D	N		100(7)			%	S0011	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige fleck			A	Y		100			%	S0004	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Cream			A	Y		100			%	S0005	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 Cream/wheat with purple fleck			A	Y		100			%	S0034	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 White/green with directional fleck			A	Y		100(7)			%	S0035	Chrysotile	5-10%	Confirmed Asbestos	NF
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige flecks			A	Y		100			%	S0030	None Detected	N.D.	None	
Other	Window	Caulking, White			A	Y		100(7)			%	S0027	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Other	Window	Caulking			A	Y		100(7)			%	S0051	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Piping		Parging Cement	Fitting		C	N		100(7)			%	S0026	Chrysotile	50-75%	Confirmed Asbestos	F
Piping		Parging Cement	Fitting		C	N		100(7)			%	S0046	Chrysotile	25-50%	Confirmed Asbestos	F
Wall		Drywall and joint compound			A	Y		100			%	S0040	None Detected	N.D.	None	
Wall		Plaster, Textured			C	Y		100			%	S0036	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	S0017	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	S0020	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	S0053	None Detected	N.D.	None	
Wall		Rubber, Black baseboards			A	Y		100			%	S0041	None Detected	N.D.	None	
Wall		Vermiculite			D	N		100(7)			%	S0022	Actinolite	25-50%	Confirmed Asbestos	F
Wall		Mastic, Brown, Black baseboards		Rubber	D	N		100			%	S0012	None Detected	N.D.	None	

Client: Halton District School Board
Location: #1984 : 1984 Samples
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Other	Window	Caulking, Black			A	Y		100(7)			%	S0015	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall		Drywall and joint compound			A	Y		100			%	S0039	None Detected	N.D.	None	
Wall		Paint, Concrete block			A	Y		100			%	S0018	None Detected	N.D.	None	
Wall		Mortar, Concrete block			D	N		100			%	S0021	None Detected	N.D.	None	
Wall		Mortar, Exterior brick			D	N		100			%	S0054	None Detected	N.D.	None	
Wall		Rubber, Brown baseboards			A	Y		100			%	S0028	None Detected	N.D.	None	
Wall		Mastic, Brown, Brown baseboards		Rubber	D	N		100			%	S0013	None Detected	N.D.	None	

Client: Halton District School Board
Location: #2009 : 2009 Samples
Survey Date: 2024-08-07

Site: Elementary Schools
Floor:

Building Name: Kilbride Public School
Room #:
Last Re-Assessment: 0000-00-00

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Vinyl Floor Tile, 12x12 Dark beige with dark beige flecks			A	Y		100			%	S0030	None Detected	N.D.	None	

Legend:

Sample number	Units	Other
S####	Asbestos sample collected	SF Square feet
L####	Paint sample collected	LF Linear feet
P####	PCB sample collected	EA Each
M####	Mould sample collected	% Percentage
V####	Material is visually identified to be identical to S####	LF Linear feet
V0000	Known non hazardous material	
V9000	Material visually identified as a Hazardous Material	
V9500	Material is presumed to be a hazardous material	
		A Access
		V Visible
		AP Air Plenum
		F Friable material
		NF Non Friable material
		PF Potentially Friable material
		Pb Lead
		Hg Mercury
		As Arsenic
		Cr Chromium

Access

A	Accessible to all building occupants
B	Accessible to maintenance and operations staff without a ladder
C	Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas
D	Not normally accessible

Condition

Good	No visible damage or deterioration
Fair	Minor, repairable damage, cracking, delamination or deterioration
Poor	Irreparable damage or deterioration with exposed and missing material

Visible

Y	The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels).
N	The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points.
L	The material is partially visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceiling system or access panels) to view completely and access. Includes partially viewed access points to crawlspaces, attic spaces, etc. without entering. Observations are limited to the extent visible from the access points.

Air Plenum

Yes or	The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation.
No	

Colour Coding

The material is a hazardous material, either by analytical results or by visible identification.
The material is presumed to be a hazardous material, based on visual appearance, and was not sampled due to limited access or the non-destructive nature of sampling.

Action

(1) Clean up of ACM Debris	(2) Precautions for Access Which may Disturb ACM Debris	(3) ACM removal
(4) Precautions for Work Which may Disturb ACM in Poor Condition	(5) Proactive ACM removal (Minimum repair required for fair condition)	(6) ACM repair

(7) Management program and surveillance